PPL Susquehanna, LLC 769 Salem Boulevard Berwick, PA 18603 Tel. 570.542.3445 Fax 570.542.1504 tsrausch@pplweb.com



JUN 2 2 2010

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Stop O-P1-17 Washington, DC 20555-0001

SUSQUEHANNA STEAM ELECTRIC STATION UNIT 1 SIXTEENTH REFUELING OUTAGE OWNER'S ACTIVITY REPORT PLA-6625

Docket No. 50-387

The attached report is for the Susquehanna Unit 1 Sixteenth Refueling Outage, which is the second Unit 1 refueling outage for the 2nd Inspection Period of the 3rd Inspection Interval for Unit 1.

The report was prepared and submitted in accordance with the requirements of ASME Code Case N-532-4.

By copy of this letter, we are transmitting the Owner's Activity Report to the Commonwealth of Pennsylvania.

If you have any questions, please contact Mr. Michael H. Crowthers, Manager - Nuclear Regulatory Affairs at (610) 774-7766.

Sincerely,

. Rausch

Attachment: Unit 1 Sixteenth Refueling Outage Owner's Activity Report

Copy: NRC Region I Mr. P. W. Finney, NRC Sr. Resident Inspector Mr. R. V. Guzman, NRC Sr. Project Manager Mr. R. R. Janati, DEP/BRP Commonwealth of Pennsylvania