

Note to File:

Associated Specialists, Inc.
License No. 47-31344-02
Docket No. 030-37941
Reference No. 030-37862
Control No. 572997

SUBJECT: Close-out of Notification Letter (Mail Control No. 572997)

On June 15, 2010, Dr. Saad Mossallati, the owner of Associated Specialists, Inc., sent in a letter informing the NRC that their RSO had left and Dr. Abdalnabi (the licensee's only authorized user) would be serving as temporary RSO. A standard acceptance of notification letter could not be sent out because the 60 days that a temporary RSO could serve had expired and the licensee did not have a permanent RSO. During this time, the licensee resumed operations, including patient studies, without a RSO in place. A Confirmatory Action Letter (CAL No. 1-10-001) was sent out on October 14, 2010, confirming that the licensee must suspend operations until a permanent RSO is authorized on their NRC license. This CAL (located in ADAMS ML102880411) closes out the notification control number 572997.

Please also note the docket number on the current license (47-31344-02) is incorrect. The correct docket number is 030-37941. Reference number 030-37862 goes back to the original license application (47-31344-01) which was voided. The docket number will need to be corrected when the amendment to change RSO is submitted.

Janice Nguyen */RA/*
Health Physicist
October 25, 2010