

U.S. NUCLEAR REGULATORY COMMISSION

Date: 12/16/2010

Time: 12:30 PM

TELEPHONE CONVERSATION RECORDMail Control
or Report No(s).

144649

License No(s).

SMB-141

Docket No(s).

04006394

Name of Licensee: Department of the Army, US Army Development and Engineering Command

Name of Participant(s): Joel Cehm, PIKA
Dennis Lawyer, DNMS

Telephone No. 510-914-6262

Subject: RAI, Revised Report

(NOTE: This will be used as the
Documents Title in ADAMS)

I discussed with Mr. Cehm that the remaining issued with the PIKA report was there were several, "See survey" which were note explained. He said that the note on the static reading summary points to the original, raw survey sheet prepared by the survey tech. It says that those survey points were inaccessible. Either the VSP survey point was above the roofline, or otherwise in space and couldn't be surveyed. They were instructed to re-locate that point to an accessible one, but that wasn't always done. Since VSP increases the required sample size by 20%, I accepted the missing readings and proceeded ahead. However, I pointed out that this needs to be described somewhere in the report.

There was a reading above the DCGL which was in a class 2 area (SU 28). This would need to be re-investigated since it was above the DCGL. It could be resurveyed with a longer count time to ensure if it is above or below the DCGL. If above, reclassify the areas into class 1 and resurvey.

Action Required: The contractor would make changes to the report and resurvey the high location and modify the survey/report as needed.

Document Availability:

 Publicly Available Non-Publicly Available Non-Sensitive
Sensitive – Privacy Act/ PII
Immediate Release Non-Sensitive Copyright
 Sensitive – Internal
 Normal Release
Date: 12/27/2010 Sensitive- Proprietary
 Sensitive – Security-Related
Delayed Release Date:SUNSI Review Completed By: Dennis Lawyer / RA /Document Accession #: ML103500439