

U.S. NUCLEAR REGULATORY COMMISSION

TELEPHONE CONVERSATION RECORD

Date: January 10, 2011

Time: 2:30 p.m.

Mail Control or Report No(s): N/A License No(s): 45-24974-01 Docket No(s): 03030462

Name of Licensee: ECS Mid-Atlantic, LLC
Name of Participant(s): Stanley Murphy (Corporate RSO) & Sattar Lodhi
Telephone No.: 703 471 8400
Subject: Inquiry about device containing Co-57
(NOTE: This will be used as the Documents Title in ADAMS)

In a letter dated December 21, 2010, the licensee stated that they identified that they possessed an XRF device containing cobalt. The device was a paint analyzer. The letter (copy attached) stated that the device was listed on its State (VA) license and wanted to know if they needed to include it in their NRC license.

I called the RSO to discuss the use of the device. He stated that the device was in storage and is not used either in Virginia or at any other area. He also stated that they have other x-ray devices that they use in its place and they will not use it at any federal facility in the future.

I informed him that it is not necessary to include it in NRC license if they will not use it at any facility that is within NRC jurisdiction.

The RSO also asked me who he should contact about taking their x-ray devices to federal facilities. I told him that NRC does not regulate these devices and he should contact the facility management about their use at the facility.

Action Required: Document.

Document Availability:

Publicly Available

Non-Publicly Available

Non-Sensitive

Non-Sensitive Copyright

Sensitive- Proprietary

Sensitive - Privacy Act (includes PII)

Sensitive - Internal

Sensitive - Security-Related

Immediate Release

Normal Release Date: 1/18/2011

Delayed Release Date:

SUNSI Review Completed By: Sattar Lodhi / RA /

Document Accession #:



ECS CORPORATE SERVICES, LLC

"Setting the Standard for Service"

Geotechnical • Construction Materials • Environmental • Facilities

December 21, 2010

U.S. Nuclear Regulatory Commission
Region I
Attn: Mr. Sattar Lodhi
475 Allendale Road
King of Prussia, PA 19406

45-24974-01
03030462

Dear Mr. Lodhi:


During an internal audit of our Chantilly office, it was noted that the office possesses an XRF device for testing the presence of lead paint that has a Cobalt source. This device is covered under our Virginia license.

The question that comes up is, should this device also be listed on the Chantilly NRC license?

The reason this question is raised is that one of our other offices has a similar device (with a Cadmium source), and it is listed on both that office's NRC and Virginia license. It appears that this may be an administrative discrepancy that needs to be addressed. I would appreciate your thoughts and guidance on how best to proceed.

Respectfully,

ECS Mid-Atlantic, LLC


Stanley J. Murphy, P.E.
Corporate Radiation Safety Officer

cc: Manol Andonyadis, Chantilly Office Manager
Mohamad Elbulok, Chantilly RSO

RECEIVED
REGION 1
2011 JAN - 3 PM 12: 51

SJM/mcc/radiation ltr 12-10.DOC