

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 02/28/2011)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME0366	RIS 'RIS 2005-02, Rev. 1 Clarifying the Process for Making Emergency Plan Changes'	O	26.0	01/08/2009	NSIR
ME3488	RIS 'Exemptions from Part 26 Subpart I Work Hours Controls Before and Immediately After a Hurricane'	O	12.0	03/08/2010	DIRS
ME4701	RIS '10 CFR 50.75 Reporting For Decommissioning Funding Status Reports'	O	6.0	09/18/2010	DPR
ME4097	RIS 'Issuance of SFST-14, Acceptance Review Process for Part 71 and 72 Licensees'	O	9.0	06/22/2010	SFST
ME4548	RIS '10 CFR Part 21 Evaluation and Reporting Requirements'	O	7.0	08/24/2010	DE
ME4841	RIS 'Adequacy of Station Electric Distribution Funding Status Report'	O	5.0	10/08/2010	DE
ME4879	RIS 'Endorsement of Revision 2 to NEI Guidance Document NEI 06-04'	O	5.0	10/14/2010	NSIR
ME4986	RIS 'Clarification for Updating Protective Action Recommendations'	O	4.0	11/08/2010	NSIR
ME5167	RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55'	O	3.0	12/13/2010	DCI
ME5728	RIS 'Status of Interactions Between the NRC and NRC Licensees During a Potential Agency Shutdown'	O	1.0	02/24/2011	DPR
ME5729	RIS 'Status of Interactions Between the NRC and NRC Licensees During Continued "Normal" Operations'	O	1.0	02/24/2011	DPR

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 02/28/2011)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME5730	RIS 'Status of Interactions Between the NRC and NRC Licensees After A Potential Agency Shutdown – Recovery'	O	1.0	02/24/2011	DPR
ME5124	IN 'Dam Failure Frequency Estimate Used in PRA is Potentially Non-Conservative'	O	4.0	11/24/2010	DRA
ME5187	IN 'Specific NRC License Required for Exports of Embargoed Destinations'	O	3.0	12/16/2010	OIP
ME5436	IN 'Gas Intrusion and Performance Issues in the Component Cooling Water System'	O	1.0	02/07/2011	DIRS
ME5682	IN 'Reactor Trips Resulting from Water Intrusion into Electrical Equipment'	O	1.0	02/15/2011	DIRS
ME5743	IN 'Control Rod Cracking Results in Reduced Design Lifetime'	O	1.0	02/28/2011	DSS
ME3680	GL 'Potential Embrittlement of Fuel Rods During a Postulated Loss-of-Coolant Accident'	O	11.0	04/01/2010	DSS
