

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7909170538 DOC. DATE: 79/09/10 NOTARIZED: NO DOCKET #
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH. NAME AUTHOR AFFILIATION
 MILLS, L.M. Tennessee Valley Authority
 RECIP. NAME RECIPIENT AFFILIATION
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards second interim rept re Penn Ventilator Co QA program.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR ENCL SIZE:
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

| | RECIPIENT ID CODE/NAME | COPIES | | RECIPIENT ID CODE/NAME | COPIES | |
|-----------|---------------------------|--------|------|---------------------------|--------|------|
| | | LTR | ENCL | | LTR | ENCL |
| ACTION: | 14 PM BOURNIA | 1 | 1 | 15 BC LWR #3 | 1 | 1 |
| | 20 LA LWR #3 | 1 | 1 | 21 AD LWR | 1 | 1 |
| INTERNAL: | 01 REG FILE | 1 | 1 | 02 NRC PDR | 1 | 1 |
| | 05 I&E | 2 | 2 | 07 EDO & STAFF | 1 | 1 |
| | 08 MPA | 1 | 1 | 09 DEPY DIR DPM | 1 | 1 |
| | 10 QAB | 1 | 1 | 11 STANDRDS DEV | 1 | 1 |
| | 12 JORDAN, E/IE | 1 | 1 | 13 FIELD COOR/IE | 1 | 1 |
| | 16 AD FOR ENGR | 1 | 1 | 17 AD PLANT SYS | 1 | 1 |
| | 17 AD REAC SFTY | 1 | 1 | 22 DIR DPM | 1 | 1 |
| | 23 OELD | 1 | 1 | AD/SITE TECH | 1 | 1 |
| | DIRECTOR DSE | 1 | 1 | GEOSCIENCES BR | 1 | 1 |
| | I&C SYS BR | 1 | 1 | MATL ENG BR | 1 | 1 |
| | MECH ENG BR | 1 | 1 | S HANAUER | 1 | 1 |
| | STRUCT ENG BR | 1 | 1 | | | |
| EXTERNAL: | 03 LPDR | 1 | 1 | 04 NSIC | 1 | 1 |
| | 24 ACRS | 16 | 16 | | | |

SEP 10 1979

SEP 18 1979

T MA 4

TOTAL NUMBER OF COPIES REQUIRED: LTR 46 ENCL 46

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 10, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - PENN VENTILATOR QA PROGRAM -
NCR QEB 79-4 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. Thomas on June 18, 1979, in accordance with 10 CFR 50.55(e). This
was followed by our first interim report dated July 16, 1979. Enclosed
is our second interim report. We expect to submit our next report by
March 21, 1980. This deficiency was reported for Sequoyah and Watts Bar
Nuclear Plants as NCR's QEB 79-2 and QEB 79-3, respectively.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stallo, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

REGULATORY DOCKET FILE COPY

7909170538

Boig
S
11