

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7910010316 DUC. DATE: 79/09/13 NOTARIZED: NO DCKET #  
 FACIL: ~~50-438~~ Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438  
50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439  
 AUTH. NAME AUTHOR AFFILIATION  
 MILLS, L.M. Tennessee Valley Authority  
 RECIP. NAME RECIPIENT AFFILIATION  
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

SUBJECT: Forwards final rept to deficiency reported on 790817 re failure to incorporate required design criteria into reactor coolant drain & vent sys.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: -----

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME	LTTR	ENCL
	14 PM	<u>BOURNIA</u>	1	1	15 BC	<u>LWR #3</u>	1	1
	20 LA	<u>LWR #3</u>	1	1	21 AD	<u>LWR</u>	1	1
INTERNAL:	01	<u>REG FILE</u>	1	1	02	NRC PDR	1	1
	05	I&E	2	2	07	EDG & STAFF	1	1
	08	MPA	1	1	09	DEPY DIR DPM	1	1
	10	GAB	1	1	11	STANDRDS DEV	1	1
	12	JORDAN, E/IE	1	1	13	FIELD COUR/IE	1	1
	16	AD FOR ENGR	1	1	17	AD PLANT SYS	1	1
	17	AD REAC SFTY	1	1	22	DIR DPM	1	1
	23	UFLD	1	1		AD/SITE TECH	1	1
		DIRECTOR DSE	1	1		GEOSCIENCES BR	1	1
		I&C SYS BR	1	1		MATL ENG BR	1	1
		MECH ENG BR	1	1		S MANAGER	1	1
		STRUCT ENG BR	1	1				
EXTERNAL:	03	LFDR	1	1	04	NSIC	1	1
	24	ACRS	16	16				

OCT 8 1979

MA  
4

T

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL 46

Wilda

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

September 13, 1979

Mr. James P. O'Reilly  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

19 SEP 19 10:34  
USNRC REGION II  
ATLANTA, GEORGIA

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - FAILURE TO INCORPORATE REQUIREMENTS OF A DESIGN CRITERIA INTO THE ACTUAL DESIGN OF THE REACTOR COOLANT DRAIN AND VENT SYSTEM - NCR BLP 79-6 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector Floyd Cantrell on August 17, 1979, in accordance with 10 CFR 50.55(e). Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

7910010 316

B019  
9/11

790201  
ORIGINAL COPY