

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912280557 DOC. DATE: 79/12/17 NOTARIZED: NO DOCKET #
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH. NAME AUTHOR AFFILIATION
 MILLS, L.M. Tennessee Valley Authority
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: Fourth interim deficiency rept re tensile anchor capacities identified lower than design allowables. No further progress on nonconformance reported. Next written rept will be submitted by 800303.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 6 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	14 PM BOURNIA	1	1	15 BC LWR #3	1	1
	20 LA LWR #3	1	1	21 AD LWR	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 QAB	1	1	11 STANDRDS DEV	1	1
	12 JORDAN, E/IE	1	1	13 FIELD COOR/IE	1	1
	16 AD FOR ENGR	1	1	17 AD PLANT SYS	1	1
	17 AD REAC SFTY	1	1	22 DIR DPM	1	1
	23 OELD	1	1	AD/SITE TECH	1	1
	DIRECTOR DSE	1	1	GEOSCIENCES BR	1	1
	I&C SYS BR	1	1	MATL ENG BR	1	1
	MECH ENG BR	1	1	POWER SYS BR	1	1
	S HANAUER	1	1	STRUCT ENG BR	1	1
	EXTERNAL:	03 LPDR	1	1	04 NSIC	1
24 ACRS		10	10			

JAN 2 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 47 ENCL 0

MA

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

December 17, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - TENSILE ANCHOR CAPACITIES
LOWER THAN DESIGN ALLOWABLES - NCR CEB 79-7 - FOURTH INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector T. Burdette on February 12, 1979, in accordance with 10 CFR 50.55(e). This was followed by our first, second, and third interim reports dated March 14, May 17, and July 30, 1979. There has been no further progress on this nonconformance to this time. We expect to submit our next written report by March 3, 1980. This deficiency was reported for Watts Bar, Sequoyah, Hartsville, and Phipps Bend Nuclear Plants.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

3019
5/10