NRC FORM 591M PART 1		U.S. NUCLEAR REGULATORY COMMISSION
(4-2008) 10 CFR 2-201		U.S. NUCLEAR REGULATORY COMMISSION
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION		
1. LICENSEE/LOCATION INSPECTED: University of Texas J.J. Pickle Research Campus Bldg 159 Nuclear Engineering and Teaching Laboratory 10100 Burnet Road Austin, TX 78712 2011- 00		 NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125
REPORT NO: 3. DOCKET NUMBER		5. DATE OF INSPECTION
070-00157	4. LICENSE NUMBER SNM-180	March 10, 2011
LICENSEE:		
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: Image		
Licensee's Statement of Corrective Actions for Item 4, above.		
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date		
LICENSEE'S REPRESENTATIVE		
NRC INSPECTOR Martha Poston-Bro	own	haithetork 3 3/15/11
NRC FORM 591M PART 1 (Rev. by RIV 3/09)		DNMS\!NMIB\BRANCH FORMS\591M FORMS\Part1 Publicly Available.doc X Public X Non-Sensitive