

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

SEP 1 2 1980

In Reply Refer To: RII:JJB 50-438/80-14 50-439/80-14

Tennessee Valley Authority
ATTN: H. G. Parris
Manager of Power
500A Chestnut Street Tower II
Chattanooga, TN 37401

## Gentlemen:

This refers to the inspection conducted by J. Blake of this office on July 21-25, 1980, of activities authorized by NRC Construction Permit Nos. CPPR-122 and CPPR-123 for the Bellefonte facility, and to the discussion of our findings held with W. R. Dahnke at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

We have examined actions you have taken with regard to previously identified enforcement matters and unresolved items. The status of these items is discussed in the enclosed report.

Two new unresolved items resulted from this inspection and are discussed in the enclosed report. These items will be examined during subsequent inspections.

During this inspection it was found that certain activities under your license appear to be in noncompliance with NRC requirements. These items and references to pertinent requirements are listed in the Notice of Violation enclosed herewith as Appendix A. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. With regard to an item concerning valve storage Item Numbers 50-438/80-14-04 and 50-439/80-14-04 corrective actions to prevent recurrence were completed prior to conclusion of this inspection; therefore, a reply is not requested for this item.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which

it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

C. E. Murphy, Chief

Reactor Construction and Engineering Support Branch

## Enclosures:

- Appendix A, Notice of Violation
- Inspection Report Nos. 50-438/80-14 and 50-439/80-14

## cc w/encl:

- A. M. Qualls, Plant Superintendent
- W. R. Dahnke, Project Manager
- J. F. Cox, Supervisor, Nuclear Licensing Section
- D. L. Terrill, Project Engineer
- H. N. Culver, Chief, Nuclear Safety Review Staff