



April 5, 2011

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Dear Sir / Madam:

Subject: VIRGIL C. SUMMER NUCLEAR STATION (VCSNS) UNIT 1  
DOCKET NO. 50-395  
OPERATING LICENSE NO. NPF-12  
ANNUAL COMMITMENT CHANGE SUMMARY REPORT

Attached please find the 2010 Commitment Change Summary Report. Commitment changes are performed in accordance with the station's Commitment Reduction Program, which was developed following NEI 99-04 "Guidelines for Managing NRC Commitment Changes".

Should you have any questions, please call Mr. Bruce Thompson at (803) 931-5042.

Very truly yours,

Thomas D. Gatlin

WCM/TDG/sr  
Attachment

c: K. B. Marsh  
S. A. Byrne  
J. B. Archie  
N. S. Carns  
J. H. Hamilton  
R. J. White  
W. M. Cherry  
V. M. McCree  
R. E. Martin  
NRC Resident Inspector  
K. M. Sutton  
NSRC  
RTS (LTD 662, RR 8850)  
File (810.46)  
PRSF (RC-11-0044)

A001  
NRK

ATTACHMENT

The following commitment reduction, with a brief justification, was performed in 2010 in accordance with VCSNS's Commitment Reduction Program, which was developed following NEI 99-04 "Guidelines for Managing NRC Commitment Changes":

**CR-10-00881**

**Commitment** – Disassemble and inspect the Turbine Driven Emergency Feedwater Pump (TDEFP) every 5 years to inspect for internal wear.

**Justification for revision** – This activity changes the frequency of an internal inspection. It does not impact the function or the performance of the TDEFP to supply feedwater to the steam generators under accident conditions, nor does it change any surveillance testing requirements or acceptance criteria. Five inspections have been performed over an approximate 25 year period with no indications of wear. The commitment to perform an internal inspection is being retained; the frequency is being extended from 5 to 10 years to be consistent with the motor-driven pumps and to reduce the potential for adversely affecting the TDEFP during maintenance teardown.