

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: The Queen's Medical Center 1301 Punchbowl Honolulu, Hawaii 96813 Location: 1301 Punchbowl, Honolulu, Hawaii REPORT NO: 2011-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
3. DOCKET NUMBER 030-38244	4. LICENSE NUMBER 53-29377-03	5. DATES OF INSPECTION February 25-28, 2011	

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

License Condition 21. B., in letter dated April 8, 2010, response #4 states that Queens' Medical Center would develop and maintain written emergency procedures to use for accelerator-specific scenarios, such as target failures, spills or releases outside a containment enclosure, delivery line failures, malfunction of air supply or exhaust systems, and high radiation levels in exhaust monitors or systems.

Contrary to the above, Queen's Medical Center failed to develop and maintain written emergency procedures as specified in letter dated April 8, 2010.

The licensee committed to develop written emergency procedures and have them approved by the licensee's management and the RSO in writing before they are fully implemented. The licensee committed completion of this evolution within thirty (30) days.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Darlena Chadwick		2/28/11
NRC INSPECTOR	R. Rick Muñoz		02/28/2011