

**R. R. Sgarro**  
Manager-Nuclear Regulatory Affairs

**PPL Bell Bend, LLC**  
38 Bomboy Lane, Suite 2  
Berwick, PA 18603  
Tel. 570.802.8102 FAX 570.802.8119  
[rrsgarro@pplweb.com](mailto:rrsgarro@pplweb.com)



April 7, 2011

ATTN: Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

**BELL BEND NUCLEAR POWER PLANT  
SUPPLEMENTAL INFORMATION AND  
ENDORSEMENT OF CCNPP UNIT 3  
RAI No. 259 QUESTION 11.02-4  
RESPONSE, FSAR CHAPTER 11  
BNP-2011-078      Docket No. 52-039**

Reference: 1) G. Gibson (UniStar Nuclear Energy) to U.S. Nuclear Regulatory Commission (NRC), "Response to Request for Additional Information for the Calvert Cliffs Nuclear Power Plant, Unit 3, RAI No. 259, UN#11-093, dated February 28, 2011 (ML110740418)

The purposes of this letter are to endorse the response made to the Request for Additional Information (RAI) by the Calvert Cliffs Nuclear Power Plant (CCNPP) Unit 3, the Reference COLA, and to provide supplemental information for RAI No. 259 sub-question 11.02-4(1).

CCNPP Unit 3 provided a response to RAI No. 259, Question 11.02-4, in Reference 1. The CCNPP Unit 3 response to RAI No. 259, Question 11.02-4, is also applicable to the BBNPP COLA and is endorsed by PPL Bell Bend, LLC (PPL) with the following supplemental information. The following supplemental information for the sub-question 11.02-4(1) response is provided to differentiate between the Quality Assurance Program Descriptions (QAPD) used at CCNPP Unit 3 and BBNPP:

In accordance with Regulatory Guide 1.143, Section 7, PPL has established and documented quality assurance program (QAP) requirements for nonsafety-related systems that meet the requirements of ANSI/ANS 55.6-1993 for Liquid Waste Management Systems (LWMS), ANSI/ANS 55.4-1993 for Gaseous Waste Management Systems (GWMS), and ANSI/ANS 40.37-2009 for Solid Waste Management Systems (SWMS). The applicable QAP requirements are implemented in accordance with the BBNPP Quality Assurance Program Description (QAPD), Section V-Nonsafety-related SSC Quality Controls.

COLA FSAR Sections 11.2.3.8, 11.3.3.7 and 11.4.6 are being revised to reflect the basis for the systems' quality assurance program.

The changes to the BBNPP FSAR will be included in a future revision of the BBNPP COLA.

D102  
MRO


The only new regulatory commitment in this letter is to update the BBNPP FSAR at a future date.

If you have any questions, please contact the undersigned at 570.802.8102.

*I declare under penalty of perjury that the foregoing is true and correct.*

Executed on April 7, 2011

Respectfully,

A handwritten signature in black ink, appearing to read "Rocco R. Sgarro". The signature is written in a cursive style with a large, stylized initial 'R'.

Rocco R. Sgarro

RRS/kw

cc: Mr. William Dean  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406-1415

Mr. Michael Canova  
Project Manager  
U.S. Nuclear Regulatory Commission  
11545 Rockville Pike T6-E55M  
Rockville, MD 20852