



830 Power Building
TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401

DEC 23 1976

Mr. Norman C. Moseley, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 818
230 Peachtree Street, NW.
Atlanta, Georgia 30303

Dear Mr. Moseley:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - NONCONFORMING SOCKET HEAD
CAP SCREWS AND SOFT MATERIAL CONDITION IN STUDS - VENDOR NCR NO. 26

The initial report of the subject condition was made to Inspector
L. E. Foster, NRC-OIE Region II office, on September 21, 1976, and
was followed by our interim report dated October 21, 1976. We expect
to submit our final written report by May 2, 1977.

Inspections and tests are continuing on the subject nonconforming
items to determine the necessary corrective action. Action has
been taken to prevent recurrence of like or similar conditions in
the future.

Very truly yours,


J. E. Gilleland
Assistant Manager of Power

CC: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

438
Misap 60