



NOTES:
 1. FOR NOTES, SEE DWG. M-038B.

LR NOTES:
 A. FOR GENERAL LICENSE RENEWAL NOTES REFER TO LR-M091-01
 B. UPDATED SI BOUNDARY IS AT THE INDICATED LOCATION, AS SHOWN ON PAID M-038C REV. 14.

LICENSE RENEWAL BOUNDARY DRAWING
LR-M038C REV. 2

SYSTEMS SHOWN ON THIS DRAWING:
 18: GASEOUS RADWASTE
 25: BORON RECOVERY

INC. DCM M-038C-10 PER MOD 92-0044	INITIALS ON FILE
INC. DCM 03-0649-00-001 REV. 00	SBV
INC. DCM M-038C-16 PER DCR 99-0001	INITIALS ON FILE
INC. DCM M-038C-15 PER DCR 96-0029	INITIALS ON FILE
INC. DCM M-038C-12 PER DCR 94-0033 (NO DWG CHANGE RECORD)	INITIALS ON FILE
INC. DCM M-038C-13 FOR RFA 94-0098	INITIALS ON FILE
INC. DCM M-038C-11 FOR RFA 94-0096	INITIALS ON FILE
ISSUED FOR FC 87-087 SUPP. 33 AS-BUILT-T-INCORP. DCM M-038-30	AZ LEB PJC PN KJT VM

BECHTEL ASSOCIATES
 PROFESSIONAL CORPORATION (OHIO)
 GAITHERSBURG, MARYLAND

DAVIS-BESSE NUCLEAR POWER STATION
 UNIT NO. 1
 THE TOLEDO EDISON COMPANY

PIPING & INSTRUMENT DIAGRAM
GASEOUS RADIOACTIVE WASTE SYSTEM

JOB NO.	DRAWING NO.	REV.
12501	M-038C	13

THIS DRAWING REV. 0 SUPERSEDES IN PART DWG. M-038 REV. 41. WORK THIS DWG. WITH M-038B.

01054