

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Tennessee Valley Authority 1101 Market Street, 6A Lookout Place Chattanooga, Tennessee 37402-2801 REPORT Nos 2011-001 & 2011-002		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
3. DOCKET NUMBER(S) 030-17797	4. LICENSE NUMBER(S) 41-06832-06	5. DATE(S) OF INSPECTION April 7, 2011	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 20.1101(c) requires that the licensee periodically (at least annually) review the radiation safety program content and implementation.



Contrary to the above, as of April 7, 2011, the licensee had not reviewed the radiation protection program annually. Specifically, since the last inspection conducted in 2010, the licensee has not performed a periodic (at least annual) review of the radiation safety program content and implementation.

This is a Severity Level IV violation (Enforcement Manual 6.3.d.3).

At the conclusion of the inspection, the Manager, Inspection Services Organization, TVA and RSO provided corrective action by stating they would develop an audit plan and conduct the annual review (audit) of the entire program in 2011.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Mike Tidwell, RSO		
NRC INSPECTOR	Craig Gordon, Sr. Health Physicist		5/13/11
BRANCH CHIEF	Blake Welling, Chief, Sec. & Ind. Branch		5/13/11