



REPLY TO
ATTENTION OF

**DEPARTMENT OF THE ARMY
WALTER REED ARMY MEDICAL CENTER
WALTER REED HEALTH CARE SYSTEM
WASHINGTON, DC 20307-5001**

June 3, 2011

Health Physics Office

Nuclear Regulatory Commission, Region 1
Medical Licensing Division
ATTN: Ms. Betsy Ullrich / Mr. James P. Dwyer
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

J-6

03001317

03001317
MAY 11 2011

Dear Sir or Madam:

Please process the following request on behalf of Walter Reed Army Medical Center (WRAMC). Pending approval of the enclosed Radiological Characterization Final Survey Report, delete the following use locations listed in Condition 10 of our Nuclear Regulatory License number 08-01738-02:

- a. Remove the Forest Glen Section and Annex, Silver Spring, MD, with the exception of building 503 (i.e., the Walter Reed Army Institute of Research) and buildings 513 and 516 (i.e., the Diamond Ordinance Radiation Facility),
- b. Remove the Gillette Building, 1413 Research Boulevard, Rockville, MD.

Two copies of the Final Status Survey Report for the Forest Glen Annex and Gillette Building which were prepared by Cabrera Services, Baltimore, MD reviewed and approved by the staff of The U.S. Army Corps of Engineers; WRAMC, Base Realignment and Closure Environmental Coordinator; WRAMC, Radiation Safety Officer (Lieutenant Colonel Francis Fota), and Colonel Casmere Taylor, Chief of Health Physics, WRAMC are enclosed for your purview and approval for amendment of our license.

For additional information, please contact Colonel Taylor at (202) 356-0058 or Lieutenant Colonel Fota at (202) 356-0061.

Sincerely,

Norvell V. Coots
Colonel Medical Corps
Commanding

Enclosures

575317
NMSS/RGN1 MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

6/3/2011, and to inform you that the initial processing which includes an administrative review has been performed.

ENVIRONMENTAL ASSESSMENT 08-01738-02
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 575317.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.