## REGULATOR INFORMATION DISTRIBUTION TEM (RIDS)

ACCESSION NBR:8309020163 DOC.DATE: 83/08/30 NOTARIZED: NO DOCKET # FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305

AUTH. NAME AUTHOR AFFILIATION

GIESLER, C.W. Wisconsin Public Service Corp. RECIPIENT AFFILIATION

VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Informs that six solenoid valves mfg by ASCO should be deleted from list of qualified equipment in Table B-1 of 830422 ltr. Valves no longer perform function important to safety & need not be environmentally qualified.

DISTRIBUTION CODE: A048S COPIES RECEIVED:LTR / ENCL SIZE:

## NOTES:

	RECIPIENT ID CODE/NAME NRR ORB1 BC 12		COPIES LTTR ENCL		RECIPIENT  ID CODE/NAME  GROTENHUIS, M 01		COPIES LTTR ENCL 1	
INTERNAL:	ELD/HDS3 IE FILE: NRR/DE/EQB NRR/DL/ORAB REG FILE	12 09 07 06 04	1 2 1 1		GC NRR CALVO,J NRR/DL DIR NRR/DSI/AEB RGN3	13	1 1 1 1	
EXTERNAL:	ACRS NRC PDR NTIS	15 02: 31	8	3 1 1	LPDR NSIC	03 05	1 1	1.4

## WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

August 30, 1983

Director of Nuclear Reactor Regulation Attention: Mr. S. A. Varga, Chief Operating Reactors Branch No. 1 Division of Licensing U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Varga:

Docket 50-305 Operating License DPR-43 Kewaunee Nuclear Power Plant Environmental Qualification of Electrical Equipment Important to Safety: Submittal Corrections

Reference:

- 1. Letter to S. A. Varga of NRC from C. W. Giesler of WPSC dated April 22, 1983
- 2. Letter to S. A. Varga of NRC from C. W. Giesler of WPSC dated March 7, 1983

Continued refinement of our Environmental Qualification program has disclosed an error in Reference 1. Six solenoid valves manufactured by ASCO, Plant IDs 33124-33126 and 33130-33132 inclusive, should be deleted from our list of qualified equipment, Table B-1 of Reference 1. These solenoid valves control the operation of our 36-inch containment purge supply and exhaust valves. In Reference 2, we committed to maintain these 36-inch valves sealed shut while above hot shutdown. Consequently, the associated solenoid valves no longer perform a function important to safety and need not be environmentally qualified per 10CFR50.49.

Very truly yours.

C. W. Giesler

Vice President - Nuclear Power

js

cc - Mr. Robert Nelson, US NRC

4078

8309020163 830830 PDR ADDCK 05000305 P PDR