ACCESSION NBR:8101130440 DUC.DATE: 81/01/09 NOTARIZED: NO DOCKET # FACIL:50=305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305

AUTHOR AFFILIATION

SMOKER, C.S. Wisconsin Public Service Corp.

RECIPIENT AFFILIATION

Region 3, Chicago, Office of the Director

SUBJECT: LER 80-042/03L-0:on 801212, during 18 diesel generator testing, air start motors failed to disengage after generator startup & shutdown. Caused by valve stem & disc corrosion. Corroded parts replaced & generator returned to svc.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR L ENCL L SIZE: L+L TITLE: Incident Reports

NOTES: 18E:3 copies all material.

05000305

ACTION:	RECIPIENT ID CODE/NAME VARGA,S. 04	COPIES LTTR ENCL 3 3	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
TAITEDALALA	A AD COMBERTOURA		A/D ENV TECH 07	4 4
INTERNALI	A/D COMP&STRU06	1 1	A/D OP REACTOOS	1 1
,	A/D MATL & QUOS	1 1	, , , , , , , , , , , , , , , , , , , ,	1 1
	A/D PLANT SYS10	1 1	A/D RAD PROT 11	į 1
	A/D SFTY ASSE12	1 · 1	A/D TECHNOLOG13	1 1 1 m
	ACC EVAL BR 14	1 1	AEOD	2 2
	ASLBP/J.HARD		AUX SYS BR 15	1 4
	CHEM ENG BR 16	1 1	CONT SYS BR 17	1 1
	CORE PERF BR 18	1 1	D/DIR, HUM FAC19	1 1
	DIR, DIV OF LIC	1 1	DIR, ENGINEERI20	1 1
	DIR, HUM FAC S21	1 1	DIR, SYS INTEG22	1 1
•	EFF TR SYS BR23	1 1	EQUIP QUAL BR25	1 1
	GEOSCIENCES 26	1 1	I&C SYS BR 29	1 1
	18E: 05	2 2	JORDAN, E./IE	1 1
	LIC GUID BR 30	1 1	LIC QUAL BR 31	1 1
	MATL ENG BR 32	1 1	MECH ENG BR 33	1 1
	MPA	3 3	NRC PDR 02	1 1
	OP EX EVAL BR34	3 3	OR ASSESS BR 35	1 1
	POWER SYS BR 36	1 1	RAD ASSESS BR39	1 1
	REACT SYS BR 40	1 1	REG FILE 01	1 1
	REL & RISK A 41	1 1	SFTY PROG EVA42	1 1
	STRUCT ENG BR44	1 1	SYS INTERAC B45	1 1
EXTERNAL:	ACRS 46	16 16	LPDR 03	1 1
	NSIC 05	1 1	TERA: DOUG MAY	1 1

IAN 14 1989

A0 4

73

73