

FEB

JUN 11

OCT

















# WARNING

- Concrete walls, ceiling, and floor of this exposure room are slightly radioactive. No drilling, cutting, grinding, chipping, jack hammering, etc.
- Personnel access is not restricted, but unnecessary presence is discouraged. Personnel dosimetry not required.
- Report any structural damage, unauthorized entry, or planned change in use or ownership to:  
Army Research Lab (ARL), (301) 394-6310,  
or Army Reactor Office (ARO), (703) 806-7861.
- Copy of permit from ARO is attached.





WARNING  
DO NOT OPEN  
DOOR  
DO NOT  
RE-ENTER  
DOOR

RADIOACTIVE  
ISOTOPE  
WASTE DECAY  
STORAGE



NOTICE:  
LOOKING CONTRACTOR  
DO NOT OPEN DOOR  
DO NOT RE-ENTER  
DOOR

CAUTION  
MISE EN GARDE  
ADVERTENCIA

CAUTION  
MISE EN GARDE  
ADVERTENCIA

CAUTION  
MISE EN GARDE  
ADVERTENCIA



MAR  
JULY  
NOV

## WAR

- Concrete walls, ceiling, and floor are slightly radioactive. No drilling, jack hammering, etc.
- Personnel access is not restricted but is discouraged. Personnel should wear protective clothing.
- Report any structural damage or change in use or ownership to the Army Research Laboratory or Army Reactor Office.
- Copy of permit from ARO.





re room are  
g, chipping,

ry presence  
d.  
ry, or planned

4-6310,  
06-7861.

APR  
AUG  
DEC







JANUARY

MAY

SEPTEMBER



















C42



C42







