

HSA BUILDING FACT SHEET

Building Number / Name: 504 / Nothing

Current Tenant / Use: None

Original / Former Use: Unknown

Date of Construction: Unknown

Construction Materials: Unknown

Total Sq. Footage: Unknown

Renovation Status: Unknown

Floors: Unknown

Current Building Status: Demolished

Sources of Information: (*References, Interviews*)

Document Reviews – CHAMMP Report, 1997

Site Visit and Interviews – Interview with Mr. Burton

Radiological Data Summary (*RCOPCs, Impacted Room(s) / Area(s), etc.*):

- Radionuclides Used/Potential RCOPCs: All
- Potentially Impacted Rooms: All
- Preliminary Dose Rate Survey (July 31, 2008): Not performed due to new WRAIR building having been constructed over top of the demolished building footprint

Current Radiological Status: No close-out documentation discovered

Site Visit Information: (*Date Toured, Site Contact, Security Issues*)

Site Contact – None

Building has been demolished, and new WRAIR building sits in the footprint; therefore, no tour was conducted during the site walk.

Preliminary MARSSIM Classification(s): Impacted

Recommendations: The Building 504 footprint can be disregarded at this time, but based on its proximity to Building 503, it should be re-visited at a later date during the decommissioning of Building 503.

Photograph(s) Taken: None (Building is demolished, and footprint is covered by new building)

Floor Plan(s) / As-built Drawing(s): None available