

A002

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-305 KEWAUNEE
RECIPIENT: KEPPLER, J.G.
ORIGINATOR: JAMES, E.W.
COMPANY NAME: WI PUB SVC
SUBJECT:

DOC DATE: 781117
ACCESSION NBR: 7811220196
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+1

LER#78-032/03L-0 on 781019:while performing monthly 4-hour full load D/G SP load on
D/G 1A drifted low & could not be raised until load was decreased to less than 2100
kw.Caused by maladjustment of cam in upper load limit switch.

NOTARIZED _____

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/3 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EER	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:
LTR 42
ENCL 42

NOV 29 1978

NOTES:

I&E 3 cys all matl Lawrence (OELD) 1 cy all matl.

A0 4
GD



P.O. Box 1200, Green Bay, Wisconsin 54305

November 17, 1978

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 78-032/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9,
the attached Licensee Event Report for reportable occurrence LER 78-032/03L-0
is being submitted.

Very truly yours,

A handwritten signature in cursive script that reads "E. W. James".

E. W. James
Senior Vice President
Power Supply & Engineering

enf

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
Dir, Office of Mgt Info & Program Control ✓
US NRC, Washington, D. C. 20555

A002
5/11

7811220196

ODC

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

November 17, 1978

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 78-032/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 78-032/03L-0 is being submitted.

Very truly yours,

E. W. James
Senior Vice President
Power Supply & Engineering

snf

Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
Dir, Office of Mgt Info & Program Control
US NRC, Washington, D. C. 20555

NOV 20 1978

dup of 781122 0196

Approved 11/21