JUN 1000



## WISCONSIN PUBLIC SERVICE CORPORATION

P.O. Box 1200, Green Bay, Wisconsin 54305

Kewauner

June 12, 1980

Mr. T. G. Keppler, Regional Director Office of Inspection and Enforcement Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 Operating License DPR-43 IE Bulletin 80-12 Decay Heat Removal System Operability

The subject bulletin, which we received on May 12, 1980, required a response within thirty days. Although we have completed our review, we have not had sufficient time to process our response, due to activities associated with our annual refueling outage. Our review has indicated that the current design is adequate. We will submit our response to the referenced bulletin within one week of the date of this letter.

Very truly yours,

Carlential

E. R. Mathews Vice President Power Supply & Engineering

ERM/d1

8007020032 Q