Upon Separation This Page is Decontrolled



SECURITY **SAFEGUARDS** INFORMATION NRC-86-14

WISCONSIN PUBLIC SERVICE CORPORATION

February 6, 1986

Mr. W. L. Axelson, Chief Materials and Safeguards Branch U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Gentlemen:

Docket 50-305 Operating/License DPR-43 Kewaunee Nuclear Power Plant Inspection Report No. 50-305/850018

Reference: Letter from W. L. Axelson (NRC) to D. C. Hintz (WPSC) dated

January 7, 1986

Inspection Report No. 50-305/850018 identified a violation of NRC requirements during a routine safeguards inspection and requested that Wisconsin Public Service Corporation (WPSC) provide a written response within thirty days. WPSC was also requested to respond to noted open items detailed in sections 4, 5 and 9 of the Inspection Report.

As required, we have attached a 30-day written response to the Notice of Violation. In addition, we are currently preparing written responses to the noted open items and shall forward these responses to you by March 10, 1986.

The attachment to this letter contains information protected under the provisions of 10 CFR 73.21, and therefore shall not be placed in the Public Document Room.

Very truly yours,

D. C. Hintz

Manager - Nuclear Power

8605010122 860425 PDR ADOCK 05000305

MSL/jms Attach.

cc - Mr. G. E. Lear, US NRC - w/o attach.

Mr. Robert Nelson, US NRC - w/o attach.

600 North Adams • P.O. Box 19002 • Green Bay, WI 5430

WPSC'[414] 433-1234 TELECÒPIER (414) 433-1297



TELEX 51010 12698 WPSC GRB EASYLINK 62891993

WISCONSIN PUBLIC SERVICE CORPORATION

600 North Adams • P.O. Box 19002 • Green Bay, WI 54307-9002

Enclosure Contains SAFEGUARDS INFÓRMATION **Upon Separation This** Page is Decontrolled

SECURITY SAFEGUARDS INFORMATIO A

March 7, 1986

Mr. W. L. Axelson, Chief Materials and Safeguards Branch U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Gentlemen:

Docket 50-305 Operating License DPR-43 Kewaunee Nuclear Power Plant Inspection Report No. 50-305/850018

- References: 1) Letter from D. C. Hintz (WPSC) to W. L. Axelson (NRC) dated February 6, 1986
 - 2) Letter from W. L. Axelson (NRC) to D. C. Hintz (WPSC) dated January 7, 1986
 - 3) Letter from S. A. Varga (NRC) to D. C. Hintz (WPSC) dated November 29, 1984
 - 4) Letter from D. C. Hintz (WPSC) to S. A. Varga (NRC) dated April 11, 1985

In accordance with the commitment made in our letter dated February 6, 1986 (reference 1), the attachment provides our response to the open items noted in IE inspection report number 50-305/85018 (reference 2).

We would like to also take this opportunity to express our concern regarding the overall accuracy of the inspection report. A detailed review of the report reveals several instances in which inconsistencies and inaccurate descriptions of commitments exist. The majority of the inconsistencies centers around the number of open items which are actually being cited, tracked, and/or requiring 🚯 our response. There are also several inconsistencies regarding the number of individuals who actually conducted the inspection. More importantly, however, is our concern regarding the inaccurate descriptions of commitments made. For ${\mathfrak G}$ example, the corrective measures stated in Sections 5a and 5b of the inspection report were not discussed with our management staff during the exit interview. These items most likely resulted from informal discussions with members of our staff while speculating possible corrective measures. Although we encourage

> SECURITY SAFEGUARDS INFORMATION

MAR 1 0 1986