Michael G. Herr, CHP Materials License Branch United States Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, IL 60532-4352

06/20/2011

Michael

Reference mail control # 574801

This is confirmation that I have never had a leaking source while licensed by NRC license 48-32333-01. Attached are most recent leak test for the two gauges covered by my license. Leaks test have been performed at 6 month intervals if gauges where actively being used.

Wisconsin License License Number 097-1136-01


Old Address on license 1800 Blueberry Dr. Plover, WI 54467

<u>New address</u> 10513 Boulder Lane Boulder Junction, WI 54512

Any questions please let me know.

Joe Keyzers RSO Metso Fabrics 10513 Boulder Lane Boulder Junction, WI 54512

Joseph Key Mesa



NRC FORM 314 U.S. NUCLEAR REGULATORY COMMISSION (12-2010) 10 CFR 30.36(j)(1); 40.42(j)(1); 70.38(j)(1); and 72.54(k)(5)(1)(1)	This submittal is used by NRC as part of released for unrestricted use. Send comme	with this mandatory collection request: 30 minutes. the basis for its determination that the facility is ents regarding burden estimate to the Information			
CERTIFICATE OF DISPOSITION OF MATERIALS	or by internet e-mail to Infocollects.Resou Information and Regulatory Affairs, NEOB- Budget, Washington, DC 20503. If a means				
LICENSEE NAME AND ADDRESS	LICENSE NUMBER	DOCKET NUMBER			
Keyzers Joseph M.	48-32333-01	0303577			
1800 Blueberry Dr. Plover, WI 54467	LICENSE EXPIRATION DATE 07/31/11				
A. LICENSE STATUS (Check the	e appropriate box)				
This license has expired. I This license has not yet expired; please					
B. DISPOSAL OF RADIOACT					
(Check the appropriate boxes and complete as necessary. If additional space is r The licensee, or any individual executing this certificate on behalf of the licens					
1. No radioactive materials have ever been procured or possessed by	the licensee under this license				
 All activities authorized by this license have ceased, and all radioact under this license number cited above have been disposed of in the 		possessed by the licensee			
 a. Transfer of radioactive materials to the licensee listed below: Joseph M. Keyzers Transferred to State of Wisconsin License 	# 097-1136-01 Have License	in State of WI since 7/7/06			
b. Disposal of radioactive materials:					
1. Directly by the licensee:					
2. By licensed disposal site:					
3. By waste contractor:					
 c. All radioactive materials have been removed such that any remai Part 20, Subpart E, and is ALARA. 	ning residual radioactivity is wi	thin the limits of 10 CFR			
C. SURVEYS PERFORMED A	ND REPORTED				
1. A radiation survey was conducted by the licensee. The survey confirmed and the survey confirmed and the survey confirmed and the survey confirmed and the survey and the survey confirmed and the survey and the survey confirmed and the survey confirmed and the survey confirmed and the survey and the survey confirmed and the survey confirmed and the survey confirmed and the survey and the survey confirmed and the survey and the survey confirmed and the survey conf	ms:				
a. the absence of licensed radioactive materials					
b. that any remaining residual radioactivity is within the limits of 10 (CFR 20, Subpart E, and is ALA	NRA.			
2. A copy of the radiation survey results:					
a. is attached; or b. is not attached (Provide explanation); or	c. was forwarded to NRC on				
✓ 3. A radiation survey is not required as only sealed sources were ever p	ossessed under this license, a	Date			
\checkmark a. The results of the latest leak test are attached; and/or	b. No leaking sources have e				
The person to be contacted regarding the information provided on this form:					
NAME Joseph M Keyzers Mail all future correspondence regarding this license to:		MAIL ADDRESS e.keyzers@metso.com			
10513 Boulder Lane, Boulder Junction, WI 54512					
C. CERTIFYING OFF		RRECT			
PRINTED NAME AND TITLE SIGNATURE	- /	DATE			
Joseph M. Keyzers Joseph M. Keyzers	They ight	6/20/11			
WARNING: FALSE STATEMENTS IN THIS CERTIFICATE MAY BE SUBJECT TO CIVIL AND/OR SUBMISSIONS TO THE NRC BE COMPLETE AND ACCURATE IN ALL MATERIAL RESPECT. 18 WILLFULLY FALSE STATEMENT OR REPRESENTATION TO ANY DEPARTMENT OR AGENCY	BU.S.C. SECTION 1001 MAKES IT A	CRIMINAL OFFENSE TO MAKE A			
NRC FORM 314 (12-2010)					

Send all kits and requests to:

SUNTRAC Services, Inc. 1818 East Main Street League City, TX 77573 (281) 338-2133

ATTN: SIT-KIT

CAUTION: Conduct a survey on the outside of each package placed in the U.S. Mails. Any reading over 0.5 mR/hr at contact with the envelope or package shall not be mailed.

LEAK TEST INVENTORY/REPORT FORM

Company Name	Tamfelt Inc.					
Address: 1800	Blueberry Dr.	City: Plover	Stat	te: WI	Zip Code:	54467
Isotope: Am 24	1		Activity: _	80		mCi
Source Serial N	D: N/A			Leak	Test Date:	04/01/11
Device Serial No): 1271			_		
Manufacturer:	Not Provided			Mode	I No.: 104P	
Smear Taken B	: Seth Ponscho	ock		_		

--- --- --- DO NOT WRITE BELOW THIS LINE

This is to certify that the above described smear/swab has been assayed at our facilities for indication of source leakage.

Our findings show the leakage to be:

ALPHA	BETA-GAMMA	
<.0001	<.0001	μCì (Wet)

Certified By:

Date: 04/05/11

Jessica Ochoa

Register Number: 1636911

Revisions: April 2006

Texas Radioactive License No. L03062

Send all kits and requests to:

SUNTRAC Services, Inc. 1818 East Main Street League City, TX 77573 (281) 338-2133

ATTN: SIT-KIT

CAUTION: Conduct a survey on the outside of each package placed in the U.S. Mails. Any reading over 0.5 mR/hr at contact with the envelope or package shall not be mailed.

LEAK TEST INVENTORY/REPORT FORM

Company N	Name: _	Tamfelt Inc. (12	975)					
Address:	1800 Blue	eberry Dr.	City:	Plover	State: WI Zip Code:		54467	
Isotope: _/	Am 241				Activity:	25		mCi
Source Ser	ial No:	NDC 104P				Leak	Test Date:	12/27/10
Device Seri	ial No:	11891						
Manufactur	er:	NDC System				Mode	No.: 104P	
Smear Take	en By:	Roy Probandt						

DO NOT WRITE BELOW THIS LINE

This is to certify that the above described smear/swab has been assayed at our facilities for indication of source leakage.

Our findings show the leakage to be:

H

 ALPHA
 BETA-GAMMA

 <.0001</td>
 <.0001</td>


 μCì (Wet)

Certified By:

Date: 01/03/11

SUNTRAC Services, Inc. Representative (Texas Radioactive License No. L03062)

1636911



Mail CUSTAL # 574801