



~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION II

245 PEACHTREE CENTER AVENUE NE, SUITE 1200
ATLANTA, GEORGIA 30303-1257

June 29, 2011

EA-11-156

Mr. Mano Nazar
Executive Vice President
Nuclear and Chief Nuclear Officer
Florida Power and Light Company
P.O. Box 14000
Juno Beach, Florida 33408-0420

SUBJECT: TURKEY POINT NUCLEAR PLANT – MATERIAL CONTROL AND
ACCOUNTING (MC&A) INSPECTION REPORT 05000250/2011402,
05000251/2011402 AND NOTICE OF VIOLATION

Dear Mr. Nazar:

On May 30, 2011, the US Nuclear Regulatory Commission (NRC) completed an inspection at your Turkey Point Units 3 and 4. The enclosed inspection report documents the inspection results, which were discussed on June 10, 2011, with Mr. Kiley and other members of your staff. The material enclosed contains Security-Related information as defined by 10 CFR 2.390(d)(1) and should be withheld from public disclosure.

The inspection examined activities conducted under your license, as they relate to material control and accountability, to confirm compliance with the commission's rules and regulations and the conditions of your license. Within these areas, the inspection consisted of selected examination of procedures and records, observations of activities, and interviews with personnel. Based on the results of this inspection, the NRC has identified an issue that was evaluated under the risk significance determination process as having very low safety significance (Green). The NRC also identified one violation associated with this issue.

The violation was evaluated in accordance with the NRC Enforcement Policy. The current Enforcement Policy is included on the NRC's Web site at (<http://www.nrc.gov/about-nrc/regulatory/enforcement/enforce-pol.html>). The violation is cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding it is described in detail in the subject inspection report. The violation is cited because not all of the criteria specified in the NRC Enforcement Policy for a non-cited violation were satisfied. Specifically, Florida Power and Light failed to restore compliance within a reasonable time after the violation was first identified in NRC Inspection Report 50-250, 251/2007-201.

~~Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s)
This transmittal document is decontrolled.~~

LIMITED INTERNAL

DISTRIBUTION PERMITTED

OFFICIAL USE ONLY – SECURITY RELATED INFORMATION

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

2

The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence, and the date when full compliance was achieved is already adequately addressed in the enclosed inspection report. Therefore, you are not required to respond to this letter unless the description herein does not accurately reflect your corrective actions or your position. In that case, or if you choose to provide additional information, you should follow the instructions specified in the enclosed Notice.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system, ADAMS. ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related information contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system, ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security Related Information-Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390 (b)(1).

Sincerely,

/RA/

Daniel W. Rich, Chief
Reactor Projects Branch 3
Division of Reactor Projects

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

Enclosures: Inspection Report 05000250/2011402, 05000251/2011402
w/Attachment: Supplemental Information (Security-Related Information)
Notice of Violation (Security-Related Information)

cc w/encl: (See next page)

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

OFFICIAL USE ONLY – SECURITY RELATED INFORMATION

The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence, and the date when full compliance was achieved is already adequately addressed in the enclosed inspection report. Therefore, you are not required to respond to this letter unless the description herein does not accurately reflect your corrective actions or your position. In that case, or if you choose to provide additional information, you should follow the instructions specified in the enclosed Notice.

Because the issue involves Security-Related Information, if you choose to respond, your response will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response Security-Related Information in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390(b)(1). In accordance with 10 CFR 2.390(b)(ii) the NRC is waiving the affidavit requirements of your response.

The material enclosed herewith contains Security-Related Information in accordance with 10 CFR 2.390(d). Its disclosure to unauthorized individuals could present a security vulnerability; therefore, the material will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Sincerely,

/RA/

Daniel W. Rich, Chief
Reactor Projects Branch 3
Division of Reactor Projects

Docket Nos. 50-250, 50-251
License Nos. DPR-31, DPR-41

Enclosure: Inspection Report 05000250/2011402, 05000251/2011402
w/Attachment: Supplemental Information (Security-Related Information)
Notice of Violation (Security-Related Information)

cc w/encl: (See page 4)

X PUBLICLY AVAILABLE NON PUBLICLY AVAILABLE X SENSITIVE X NON-SENSITIVE
ADAMS: X Yes ACCESSION NUMBER: ML111800515 X SUNSI REVIEW COMPLETE X FORM 665 ATTACHED

OFFICE	RII:DRP	RII:DRP	RII:EICS	RII:DRP			
SIGNATURE	GJW	DWR1	SES	JSS1 by email			
NAME	GWilson	DRich	SSparks	S. Stewart			
DATE	06/23/2011	06/29/2011	06/24/2011	06/28/2011			
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY DOCUMENT NAME: G:\DRPI\RPB3\TURKEY POINT\REPORTS\2011\2011402
MCA OOU INSP DRAFT.DOCX

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

3

cc w/encl:

Michael Kiley
Site Vice President
Turkey Point Nuclear Plant
Florida Power and Light Company
9760 SW 344th Street
Florida City, FL 33035

Brent Rittmer
Security Manager
Turkey Point Nuclear Plant
Florida Power & Light Company
9760 SW 344th Street
Florida City, FL 33035

cc w/o encl:

Alison Brown
Nuclear Licensing
Florida Power & Light Company
Electronic Mail Distribution

Larry Nicholson
Director
Licensing
Florida Power & Light Company
Electronic Mail Distribution

Michael Kiley
Site Vice President
Turkey Point Nuclear Plant
Florida Power and Light Company
Electronic Mail Distribution

Niel Batista
Emergency Management Coordinator
Department of Emergency Management
and Homeland Security
Electronic Mail Distribution

Robert J. Tomonto
Licensing Manager
Turkey Point Nuclear Plant
Florida Power & Light Company
Electronic Mail Distribution

Eric McCartney
Plant General Manager
Turkey Point Nuclear Plant
Florida Power and Light Company
Electronic Mail Distribution

Mitch S. Ross
Vice President and Associate General
Counsel
Florida Power & Light Company
Electronic Mail Distribution

Marjan Mashhadi
Senior Attorney
Florida Power & Light Company
Electronic Mail Distribution

William A. Passetti
Chief
Florida Bureau of Radiation Control
Department of Health
Electronic Mail Distribution

Ruben D. Almaguer
Director
Division of Emergency Preparedness
Department of Community Affairs
Electronic Mail Distribution

Mano Nazar
Executive Vice President and Chief Nuclear
Officer
Nuclear Division
Florida Power & Light Company
P.O. Box 14000
Juno Beach, FL 33408

Senior Resident Inspector
Turkey Point Nuclear Generating Station
U.S. Nuclear Regulatory Commission
9762 SW 344th St.
Florida City, FL 33035

cc w/o encl. (continued next page)

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

cc w/o encl. (continued)

Attorney General
Department of Legal Affairs
The Capitol PL-01
Tallahassee, FL 32399-1050

Mike A. Shehadeh, P.E.
City Manager
City of Homestead
Electronic Mail Distribution

County Manager of Miami-Dade County
111 NW 1st Street, 29th Floor
Miami, FL 33128

Gene St. Pierre
Vice President, Fleet Support
Florida Power & Light Company
Electronic Mail Distribution

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

5

Letter to Mano Nazar from Daniel W. Rich dated June 29, 2011

SUBJECT: TURKEY POINT NUCLEAR PLANT – MATERIAL CONTROL AND
ACCOUNTING (MC&A) INSPECTION REPORT 05000250/2011402,
05000251/2011402 AND NOTICE OF VIOLATION

Distribution w/encl:

C. Evans, RII EICS

L. Douglas, RII EICS

OE Mail

RIDSNRRDIRS

RidsNrrPMTurkeyPoint Resource

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~