ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATO INFORMATION DISTRIBUTION (RIDS)

						_				
FACIL:50 AUTH.N SCHROCK	,C.A. Wis	ee Nucl JTHOR A sconsin ECIPIEN	ear Powe FFILIAT Public T AFFIL	er Pla ION Servi IATION	nnt, Wis ce Corp I	sconsin	Publi	c Ser	vic	DOCKET 0500030
	L	ocumen	t Contro	or Bra	inch (Do	ocument	Contr	or De	sk)	
SUBJECT	: Notifies the Superintend responsibilities.	lent -	Plant Qu	uality	Progra	ams will	exch	ange		
	UTION CODE: M Changes of Pe				ED:LTR	ENCL	0	SIZE:	2	
NOTES:										
	RECIPIENT ID CODE/NA PD3-3 LA HANSEN,A.		COPIES LTTR EN			IPIENT DDE/NAME PD	٠	COPI LTTR 1		
INTERNAL:	ACRS ASLBP OC/LFDCB REG FILE	01	1 1 1 1	 - 	ADM/PMS CAA-16E OGC/HDS SECY/DS	3-13 51		1 1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

EXTERNAL: NRC PDR

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

MAJUP

R

I

D

D

D.

Ĭ

D

D

WPSC (414) 433-1598 TELECOPIER (414) 433-5544



NRC-93-124 EASYLINK 62891993

600 North Adams • P.O. Box 19002 • Green Bay, WI 54307-9002

August 13, 1993

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, D.C. 20555

Ladies/Gentlemen:

Docket 50-305
Operating License DPR-43
Kewaunee Nuclear Power Plant
Personnel Change

This letter provides notification of a personnel change at Wisconsin Public Service Corporation (WPSC). Prior to the end of 1993, the Superintendent - Quality Assurance and the Superintendent - Plant Quality Programs, will exchange responsibilities and titles. Following is a description of both positions.

The San San San San San San

i godina o mostali i za traza kati

Superintendent - Quality Assurance

The Superintendent - Plant Quality Programs will assume the position of Superintendent - Quality Assurance. The Superintendent - Quality Assurance is responsible to the Senior Vice President - Nuclear Power for ensuring that an Operational Quality Assurance Program is developed, implemented, and maintained to meet the licensing requirements and management objectives. He is responsible for final review of changes to the OQAP and for final approval of changes to the Quality Assurance Directives. He is responsible for review of directives which control activities affecting quality. He is independent of cost and scheduling considerations and has the authority and organizational freedom to identify quality problems, stop work on non-conforming activities associated with plant operations until deficiencies have been corrected; initiate, recommend or provide solutions, and verify implementation of corrective actions. The Superintendent - Quality Assurance maintains stop work authority for nonconforming activities associated with plant operations by reporting them to the Senior Vice President - Nuclear Power.

170078 9308170147 930813 PDR ADDCK 05000305 H PDR WOOP 10

Document Control Desk August 13, 1993 Page 2

He has responsibility for ensuring that functions and activities of the Quality Assurance Staff are controlled and performed in accordance with approved directives which implement the requirements of the OQAP.

The Superintendent - Quality Assurance shall, as a minimum, meet the requirements of ANSI N18.1-1971 and should have a minimum of a B.S. degree in Science or Engineering from an accredited college or university, a minimum of five years experience in power plant construction, engineering and/or plant operation, and a familiarity with codes and regulations.

Superintendent - Plant Quality Programs

The Superintendent - Quality Assurance will assume the position of Superintendent - Plant Quality Programs. This position is responsible to the Manager - Nuclear Plant Support Services and has been delegated the responsibility for verifying the effectiveness of plant quality activities and has the onsite Quality Control Group reporting to him. He is responsible for review of nuclear administrative directives for consistency with the OQAP. He has the authority and organizational freedom to identify quality problems, initiate, recommend or provide solutions, and verify implementation of corrective actions. He is responsible for the administration and implementation of Inservice Inspection, steam generator inspection services, and Quality Engineering activities. He has a direct communications link to the corporate QA staff in matters affecting quality.

No additional organizational changes are anticipated in conjunction with these changes. WPSC has concluded that this change strengthens the WPSC organization, is administrative in nature, and does not involve a safety concern. This change does not affect the Operational Quality Assurance Program Description or the KNPP Technical Specifications.

Sincerely,

C. A. Schrock

C. G. School

Manager - Nuclear Engineering

BJD/cjt

cc - US NRC, Region III
US NRC Senior Resident Inspector

LIC\NRC\31.WP