

PRIORITY 1
ACCELERATED RIDS PROCESSING

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9506190313 DOC.DATE: 95/06/12 NOTARIZED: YES DOCKET #
FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Service 05000305
AUTH.NAME AUTHOR AFFILIATION
STEINHARDT,C.R. Wisconsin Public Service Corp.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Informs of mod & surveillance test performed during recently completed Spring 1995 refueling outage.

DISTRIBUTION CODE: A030D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 2
TITLE: Generic Ltr-93-04-Rod Control System Failure & Withdrawal of Rod Cont

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	LAUFER, R	1		
INTERNAL:	FILE CENTER 01	1	NRR/DRCH/HICB	1
	NRR/DRPW/PDIV-1	1	NRR/DSSA/SRXB	1
EXTERNAL:	NRC PDR	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 6 ENCL 0

P
R
I
O
R
I
T
Y

1

D
O
C
U
M
E
N
T



WPSC (414) 433-1598
TELECOPIER (414) 433-5544

WISCONSIN PUBLIC SERVICE CORPORATION

600 North Adams • P.O. Box 19002 • Green Bay, WI 54307-9002

June 12, 1995

50.54(f)

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Gentlemen:

Docket 50-305
Operating License DPR-43
Kewaunee Nuclear Power Plant
NRC Generic Letter 93-04 Closeout

- References:
- 1) Letter from C. R. Steinhardt (WPSC) to Document Control Desk (NRC) dated September 20, 1993
 - 2) Letter from R. J. Laufer (NRC) to C. A. Schrock (WPSC) dated December 7, 1994
 - 3) Letter from C. R. Steinhardt (WPSC) to Document Control Desk (NRC) dated January 12, 1995

Reference 1 provided Wisconsin Public Service Corporation's (WPSC) response to Generic Letter (GL) 93-04 "Rod Control System Failure and Withdrawal of Rod Control Cluster Assemblies, 10 CFR 50.54(f)". In this response WPSC committed to implement the current order surveillance test and evaluate the current order timing modification.

In response to the NRC's request for additional information (references 2&3), WPSC agreed to perform the current order timing modification and surveillance test consisting of current order traces of one rod per group at the power cabinet.

This letter is to: 1) inform you that the modification and surveillance test were performed during the recently completed Spring 1995 refueling outage, and 2) reaffirm our commitment to perform the surveillance test each refueling outage.


9506190313 950612
PDR ADOCK 05000305
P PDR

A030 / 0

Document Control Desk
June 12, 1995
Page 2

If you have any questions or need additional information, please contact a member of my staff.

Sincerely,




C. R. Steinhardt
Senior Vice President - Nuclear Power

RPP/jmf

cc - US NRC Region III
US NRC Senior Resident Inspector

Subscribed and Sworn to
Before Me This 12th Day
of June 1995



Notary Public, State of Wisconsin

My Commission Expires:
June 18, 1995