

**Comanche Peak Nuclear Power Plant, Units 3 & 4
COL Application
Part 2, FSAR**




Figure 2.5.1-220 Faults Cutting Marble Falls Horizon A