

FROM: Iowa Electrifi Light & Power Company Cedar Rapids, Iowa G. G. Hunt			DATE OF DOC: 6-19-74	DATE REC'D 6-29-74	LTR X	TWX	RPT	OTHER
TO: Mrs. Keppler			ORIG 1 signed	CC	OTHER	SENT AEC PDR _____ X SENT LOCAL PDR _____ X		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-331		
	XXXXX							

DESCRIPTION:
Ltr re Abnormal Occurrence onc6-15-74.....
advising that an investigation of the occurrence
has determined that the pins were correctly
installed in the pressure sensing line.....

ENCLOSURES:

ACKNOWLEDGED
Do Not Remove

PLANT NAME: Duane Arnold

FOR ACTION/INFORMATION

7-5-74

AB

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	G. LEAR W/ 7 Copies
PARR(L) W/ Copies	VASSAROLI(L) W/ Copies	KELCHER(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	PURPLE(L) W/ Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>LIC ASST</u>	<u>A/T IND</u>
✓ AEC PDR	✓ HENDRIE	GRIMES		BRAITMAN
✓ OGC, ROOM P-506A	✓ SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	B. HURT
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSSO	✓ PAWLICKI	SPANGLER	KREUTZER (E)	MCDONALD
BOYD	✓ SHAO		LEE (L)	CHAPMAN
MCORE (L)(EWR)	✓ STELLO	<u>ENVIRO</u>	MAIGRET (L)	DUBE w/input
DEYOUNG(L)(PWR)	✓ HOUSTON	MULLER	REED (E)	E. COUPE
SKOVHOLT (L)	✓ NOVAK	DICKER	SERVICE (L)	
✓ COLLER(L)	✓ ROSS	KNIGHTON	SHEPPARD (L)	✓ D. THOMPSON (2)
P. COLLINS	✓ IPPOLITO	YOUNGBLOOD	SLATER (E)	✓ KLECKER
DENISE	✓ TEDESCO	REGAN	SMITH (L)	✓ EISENHUT
REG OPR	✓ LONG	PROJECT LDR	✓ TEETS (L)	
✓ FILE & REGION(3)	✓ IAINAS		WILLIAMS (E)	
✓ MORRIS	✓ BENAROYA	HARLESS	WILSON (L)	
✓ STEELE	✓ VOLIMER			

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR Cedar, Rapids, Iowa	(1)(2)(10)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓ 1 - TIC (ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-LIBRARIAN
✓ 1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
1 - P. R. DAVIS (AEROJET NUCLEAR)	NEWARK/BLUME/AGBABIAN	RM-B-127, GT.
✓ 16 - CYS ACRS XXXXXX SENT TO LIC ASST. S. TEETS	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT
	1-B & M SWINEBROAD, Rm E-201 GT	

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA

DUANE ARNOLD ENERGY CENTER

PALO, IOWA

JUNE 19, 1974

DAEC - 74 - 228

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

50 - 331



SUBJECT: Abnormal Occurrence reported to USAEC
Region III on June 15, 1974.
FILE: A-118a

Dear Mr. Keppler:


On June 15, 1974, your office was notified by telephone and telegram that an Abnormal Occurrence took place at the Duane Arnold Energy Center on June 14, 1974. We reported that the occurrence (DPR 49/74-12) involved the discovery of incorrectly installed pins in pressure sensing line snubbers in HPCI and RCIC High Flow Isolation instrumentation.

The purpose of this letter is to advise you that an investigation of the occurrence has determined that the pins were correctly installed in the pressure sensing line snubbers and that our earlier report of an Abnormal Occurrence should be disregarded. The earlier report was based on information provided by the supplier of the snubbers, and after contacting the manufacturer, it was determined that the information was incorrect.

We apologize for any inconvenience caused by this matter.

Yours very truly,

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center



DLW/GGH/bh

CC: John O'Leary	D. L. Wilson
C. W. Sandford	H. W. Rehrauer-Chairman-Safety Committee
J. A. Wallace	L. D. Root
E. L. Hammond	J. R. Newman
B. R. York	B. L. Hopkins

JUN 24 1974

5987