

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 7723
FILE: INCIDENT REPORT FILE

FROM: Iowa Electric Light & Power Cedar Rapids, Ia GG Hunt		DATE OF DOC 7-14-75	DATE REC'D 7-21-75	LTR XXX	TWX	RPT	OTHER
TO: Mr Keppler		ORIG one single	CC	OTHER	SENT AEC PDR		XX
					SENT LOCAL PDR		XX
CLASS	UNCLASS XXXXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

DESCRIPTION:

Ltr reporting abnormal occurrence on 7-12-75 concerning an inoperable drywell floor drain outboard isolation valve.....

PLANT NAME:

ENCLOSURES:

DO NOT REMOVE
ACKNOWLEDGED

FOR ACTION/INFORMATION

- | | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)
W/ Copies | SCHWENCER (L)
W/ Copies | ZIEMANN (L)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (L)
W/ Copies | STOLZ (L)
W/ Copies | DICKER (E)
W/ Copies | LEAR (L)
W/ Copies |
| PARR (L)
W/ Copies | VASSALLO (L)
W/ Copies | KNIGHTON (E)
W/ Copies | SPELS
W/ Copies |
| KNIEL (L)
W/ Copies | PURPLE (L)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

- | | | | | |
|---|---|---|---|---|
| <u>REG FILE</u>
NRC PDR
OGC, ROOM P-506A
GOSSICK/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (L)
DEYOUNG (L)
SKOVHOLT (L)
GOLLER (L) (Ltr)
P. COLLINS
DENISE
REG OPR
FILE & REGION (2)
MIPC/PE (3)
STEELE | <u>TECH REVIEW</u>
SCHROEDER
MACCARY
KNIGHT
PAWLICKI
SHAO
** STELLO
** HOUSTON
** NOVAK
ROSS
IPPOLITO
TEDESCO
J. COLLINS
LAINAS
BENAROYA
VOLLMER | DENTON
** GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR

HARLESS | <u>LIC ASST</u>
R. DIGGS (L)
H. GEARIN (L)
E. GOULBOURNE (L)
P. KREUTZER (E)
J. LEE (L)
M. RUSHBROOK (L)
S. REED (E)
M. SERVICE (L)
S. SHEPPARD (L)
M. SLATER (E)
H. SMITH (L)
S. TEETS (L)
G. WILLIAMS (E)
V. WILSON (L)
R. INGRAM (L)
M. DUNCAN (E) | <u>A/T IND.</u>
BRAITMAN
SALTZMAN
MELTZ

PLANS
MCDONALD
CHAPMAN
DUBE (Ltr)
E. COUPE
PETERSON
HARTFIELD (2)
KLECKER
EISENHUT
WIGGINTON

F. WILLIAMS
HANAUER |
|---|---|---|---|---|

EXTERNAL DISTRIBUTION

- | | | |
|--|--------------------------------|---|
| 1 - LOCAL PDR <u>Cedar Rapids, Ia</u> | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT |
| 1 - Newton Anderson | | 1 - J. D. RUNKLES, Rm E-201
GT |
| 5 - ACRS SENT TO LIC ASST <u>Teets</u> | | |
| ** SEND ONLY TEN DAY REPORTS | | |


REGULATORY DOCKET FILE COPY
IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
JULY 14, 1975
DAEC -75 -283

50-331

Mr. James Keppler, Director
Office of Inspection and Enforcement-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137




SUBJECT: Abnormal Occurrence

FILE: A-110, A-118a

Dear Mr. Keppler:

In accordance with the DAEC Technical Specifications, Section 6.11.2.A.1, this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on July 12, 1975. Mr. C. Feierabend of your office was notified of the occurrence during his site inspection on July 12, 1975.



Identification of Occurrence

Inoperable Drywell Floor Drain Outboard Isolation Valve, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and 3.7.D.1.

Description of Occurrence

During the performance of Surveillance Test Procedure No. 47D003, Drywell Floor Drain Outboard Isolation Valve CV-3705 did not fully close.

The plant was in a shutdown condition at the time the surveillance test was performed and will remain in that condition until repair of the valve and retesting is complete.

Investigation is continuing.

A formal written report will be submitted to the Office of Inspection and Enforcement within 10 days of the subject abnormal occurrence.

Very truly yours,

A handwritten signature in black ink, appearing to read "G. G. Hunt".

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

7723

DLW/GGH/mg

cc: B. C. Rusche, C. W. Sandford, J. A. Wallace, L. D. Root, E. L. Hammond,
H. W. Rehrauer, B. R. York, R. R. Rinderman, G. A. Cook, D. L. Wilson

JUL 17 1975

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: **7443**
FILE: INCIDENT REPORT FILE

FROM: Iowa Electric Light & Pwr. Co. Cedar Rapids, Iowa G.G. Hunt		DATE OF DOC 7-10-75	DATE REC'D 7-16-75	LTR XXX	TWX	RPT	OTHER
TO: James G. Keppler		ORIG 1 Signed	CC	OTHER	SENT AEC PDR <u>XXXX</u>		
CLASS UNCLASS XXX		PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

DESCRIPTION:
A/O # 75-35, ...advising the investigation of the occurrence has not been completed...will submit a complete written report after the investigation & corrective actions have been completed.....

ENCLOSURES:

**ACKNOWLEDGED
DO NOT REMOVE**

(1 cy. ltr. rec'd)

PLANT NAME: Duane Arnold

FOR ACTION/INFORMATION

VCR 7-23-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	--	--	---	--


EXTERNAL DISTRIBUTION

- | | | |
|--|--------------------------------|---|
| 1 - LOCAL PDR <i>Cedar Rapids Iowa</i> | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN)
Rm B-127 GT |
| 1 - Newton Anderson | | 1 - J. D. RUNKLES, Rm E-201
GT |
| 5 - ACRS SENT TO LIC ASST <i>Teets</i> | | |
| ** SEND ONLY TEN DAY REPORTS | | |

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office


CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
JULY 10, 1975
DAEC -75 -280



Mr. James G. Keppler, Director
Office of Inspection and Enforcement - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Abnormal Occurrence AO 50-331/75-35
Preliminary Report

File: A-110, A-118a



Dear Mr. Keppler:

On July 1, 1975 your office was notified of an abnormal occurrence at the Duane Arnold Energy Center involving missing "U" bolt restraints on certain relief valve blowdown lines (ramshead) in the pressure suppression chamber. This letter is to advise you that investigation of the occurrence has not been completed and that a complete written report on the occurrence will be submitted after the investigation and corrective actions have been completed.

Reactor operation will not resume until a stress analysis on the relief valve blowdown lines has been performed and corrective actions have been completed.

Yours truly,

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

DLW/GGH/mg

cc: B. C. Rusche
C. W. Sandford
J. A. Wallace
L. Liu
H. W. Rehrauer - Chairman, Safety Committee
J. R. Newman
E. L. Hammond

JUL 16 1975

7443

50-331/75-38

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
JULY 10, 1975
DAEC -75 -280



Mr. James G. Keppler, Director
Office of Inspection and Enforcement - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Abnormal Occurrence AO 50-331/75-35
Preliminary Report

File: A-110, A-118a

Dear Mr. Keppler:

On July 1, 1975 your office was notified of an abnormal occurrence at the Duane Arnold Energy Center involving missing "U" bolt restraints on certain relief valve blowdown lines (ramshead) in the pressure suppression chamber. This letter is to advise you that investigation of the occurrence has not been completed and that a complete written report on the occurrence will be submitted after the investigation and corrective actions have been completed.

Reactor operation will not resume until a stress analysis on the relief valve blowdown lines has been performed and corrective actions have been completed.

Yours truly,

G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

DLW/GGH/mg

- cc: (B. C. Rusche)
- C. W. Sandford
- J. A. Wallace
- L. Liu
- H. W. Rehrauer - Chairman, Safety Committee
- J. R. Newman
- E. L. Hammond

