e e e e e e e e e e e e e e e e e e e	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	I A D A C 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 57 CAT 58
O 1 7 8	REPORT LL 6 0 15 0 0 0 3 3 1 7 1 12 12 7 7 18 8 0 11 12 6 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	Core loading was conducted from Dec. 25 to Dec. 31 with stby diesel gen.
0 3	1G-21 inop. for maintenance and without testing redundant stby diesel g
0 4	Len. 1G-31. Tech Spec 3.7.C requires secondary containment be maintained
0 5	while moving fuel. T.S. 3.7.B requires both trains of the standby gas tr
0 6	<u>leatment system and associated diesel gen. be operable when sec. containm</u>
0 7	ent is required. If one stby diesel is found inop, when moving fuel imme
08	<u> diate and daily tests of the redundant diesel and SBGT sys. is required.</u>
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE E E 11
	Type No. Code Type No. No.
10	Personnel misunderstanding of Technical Specification requirements. In o
11	L rder to help preclude reoccurrence a summary of Technical Specification r
1 2	equirements will be prepared which delineates for each plant mode which
1 3	equipment must be operable and what actions are required when a specific
	<u>piece of equipment is made or found inoperable.</u>
1 5	G 28 0 0 0 0 29 NA ATOM OPERATOR OF DISCOVERY DESCRIPTION 32 G 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
1 6	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 NA NA PERSONNEL EXPOSURES 44 45
1 7	NUMBER TYPE DESCRIPTION (39) 0 0 0 0 37 Z 38 NA 9 PERSONNEL INJURIES 13
1 8	NUMBER DESCRIPTION (41) 0 0 0 0 0 0 NA Dupc of 7902020240 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	Z 42 NA
2 0	PUBLICITY SSUED DESCRIPTION 45 NRC USE ONLY NR USE ONLY NR USE ONLY
. 8	9 10 68 69 80.5 NAME OF PREPARER J. Van Sicke] PHONE: 319-851-5611