NRC FORM 195		U.S. NU	CLEAR R	EGULATORY CON SSIO	N DOCKET NUMBER 50 - 331
	T 50 DOCKET MATERIAL			FILE-NUMBER INCIDENT REPORT	
TO: Mr. James G. Keppler		FROM Towa Elect. Light & Power Co. Cedar Rapids, Towa 52406 Ellery L. Hammond			
					DATE RECEIVED 04-20-77
©LETTER □NOTORIZED □ORIGINAL □UNCLASSIFIED ☑COPY		PROP INPUT FOR		INPUT FORM	NUMBER OF COPIES RECEIVED
DESCRIPTION	· · ·		ENCLOS		
Ltr. Trans The Following:				03-29-77 concern pression chamber	ent Report (RO-50-331/77-2) ing, "A" RHR system suction strainer was foun torn, from unknown cause
ACKNOWLEDGED				l page)	
PLANT NAME: DUANE ARNOI	. D				
	e e e e e e e e e e e e e e e e e e e			•	
NOTE: IF PERSONNEL EXTEND DIRECTLY TO					XPOSURE IS INVOLVED TO KREGER/J. COLLINS
DONOT REMOVE					enal.
1		FOR ACTION/	INFORM	IATION	
BRANCH CHIEF: W/3 CYS FOR ACTION	1 12 5 6 6				
LIC. ASST.:	PARR		-		
W/ CYS ACRS CYS HOLDING/SENT AS. CAR. E					
		INTERNAL	LICT DID	ITION	
REG FILE	1	INTERNAL	I I I I I I I I I I I I I I I I I I I	JIION	
NRC PDR					
I & E (2) MIPC	11 Fall 10 A				
SCHROEDER/IPPOLITO					
HOUSTON NOVAK/CHECK					
GRIMES					
CASE BUTLER					
HANAUER			 		
TEDESCO/MACCARY					
EISENHUT BAER					
SHAO			 		
VOLLMER/BUNCH					
KREGER/J. COLLINS					
	EVTERNAL	DISTRIBUTION			CONTROL NUMBER
EXTERNAL DISTRIBUTION LPDR: CEDAR SAPADS T A TIC:					CONTROL NOWBER
NSIC:					77/1/0006
					RO !
		·			- 60

A. Zunar.

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER

P. O. Box 351

Cedar Rapids, Iowa 52406

April 11, 1977

REGULATORY DOCKET FILE COP DAEC -77 - 226

Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission-Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137



Subject: Licensee Event Report No. 77-25

(14 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

ELHammord/ Ellery L. Hammond

Chief Engineer Duane Arnold Energy Center

Docket 50-331

attachment ELH/JVS/M

Director, Office of Inspection and Enforcement (40)

U. S. Nuclear Regulatory Commission

Washington, D.C. 20555

Director, Management Information and Program Control (3) U. S. Nuclear Regulatory Commission Washington, D.C. 20555

ICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT ALL REQUIRED INFORMATION) LICENSEE LICENSE EVENT NAME LICENSE NUMBER 0 01 01 0 1 1 1 REPORT TYPE REPORT CATEGORY OOCKET NUMBER EVENT DATE REPORT DATE 0 1 CON'T 0 0 | -0 3|1 3 Ö 0 1 4 11 **EVENT OESCRIPTION** During suppression chamber inspection the "A" RHR system suppression ch 8 9 80 old amber suction strainer was found to be deformed and torn. No evidence w B 9 80 04 as found to indicate any portion of the strainer had carried away. 8 9 80 05 RHR system strainer intact. New strainer of like design is being fabri 80 cated for installation prior to end of current outage. (RO 77-25) 06 80 PRIME CAUSE SYSTEM COMPONENT COMPONENT MANUFACTURER COMPONENT CODE VIOLATION 9 | 9 | N 8 9 10 43 CAUSE DESCRIPTION 06 Unknown. Investigation continuing. Supplemental report will be 80 09 submitted. 8 80 10 80 **FACILITY** METHDD DF STATUS % POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION I H I0 0 В Surveillance Test 13 45 80 FORM OF CONTENT ACTIVITY RELEASED RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE 1 2 Z NA NA 10 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 0 0 0 Z NA 12 13 80 PERSONNEL INJURIES NUMBER DESCRIPTION 0 0 0 NA 12 80 OFFSITE CONSEQUENCES NA 8 9 80 LOSS OR DAMAGE TO FACILITY DESCRIPTION TYPE NA 10 80 **PUBLICITY** [1]7] NA 80 **ADDITIONAL FACTORS** 18 NA 80

J. Van Sickel

NAME:

GPO 881.667

319-851-5611

PHONE:

80