

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr. James G. Keppler

FROM: Iowa Elect. Light & Power Co.
Cedar Rapids, Iowa 52406
Ellery L. Hammond

DATE OF DOCUMENT
06-10-77

DATE RECEIVED
06-21-77

LETTER NOTORIZED
 ORIGINAL UNCLASSIFIED
 COPY

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
1 SIGNED

DESCRIPTION

1 page

PLANT NAME: DUANE ARNOLD
jcm 06-22-77

ENCLOSURE Licensee Event Report (R0-50-331/77-38) on 05-15-77 concerning Inerting of torus not completed within 24 hours after going to runmode due to additional nitrogen required for inerting was not ordered in sufficient time to ensure inerting completion....

1 page

**ACKNOWLEDGED
DO NOT REMOVE**

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:	<i>Lear</i>
W/3 CYS FOR ACTION	
LIC. ASST.:	<i>Parrish</i>
W/1 CYS	
ACRS 16 CYS HOLDING/SENT	<i>As CAT B</i>

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/> REG FILE				
NRC PDR				
I & E (2)				
MIPC				
SCHROEDER/IPPOLITO				
HOUSTON				
NOVAK/CHECK				
GRIMES				
BUTLER				
HANAUER				
TEDESCO/MACCARY				
EISENHUT				
BAER				
SHAO				
VOLLMER/BUNGH				
KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

LPDR: Cedar Rapids, Ia			
TIC:			
NSIC:			

CONTROL NUMBER

771740102

60

D. L. Luman

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
June 10, 1977
DAEC-77 - 318



Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission - Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. RO 77-38
(30 day)

File: A-118a

Dear Mr. Keppler:

REGULATORY DOCKET FILE COPY

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond
Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

ELH/DLW/mg

cc: Director, Office of Inspection and Enforcement (30)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

JUN 13 1977

771740102

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME:

01	I	A	D	A	C	1
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	3
---	---

REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	3	3	1
---	---	---	---	---	---	---	---

 EVENT DATE:

0	5	1	5	7	7
---	---	---	---	---	---

 REPORT DATE:

0	6	0	9	7	7
---	---	---	---	---	---

EVENT DESCRIPTION

02 Inerting of torus not completed within 24 hours after going to runmode.
03 Inerting was completed 69 minutes later after liquid nitrogen shipment
04 was recieved. Step will be added to startup procedures requiring a
05 verification, prior to startup, of adequate nitrogen supply available
06 in storage or on order. (RO 77-38)

SYSTEM CODE:

S	E
---	---

 CAUSE CODE:

D

 COMPONENT CODE:

Z	Z	Z	Z	Z	Z
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

Z

 COMPONENT MANUFACTURER:

Z	9	9	9
---	---	---	---

 VIOLATION:

Y

CAUSE DESCRIPTION

08 Additional nitrogen required for inerting was not ordered in sufficient
09 time to ensure inerting would be complete within 24 hours after going
10 to run mode.

FACILITY STATUS:

F

 % POWER:

0	3	5
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

A

 DISCOVERY DESCRIPTION:

NA

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

OFFSITE CONSEQUENCES

NA

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

NA

ADDITIONAL FACTORS

NA

NA

NAME: D. Wilson PHONE: 319-851-5611

RECEIVED DOCUMENT
PROCESSING UNIT

1977 JUN 21 PM 3 11