## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

CESSION NBR:8805040405 DOC.DATE: 88/04/26 NOTARIZED: NO DOCKET # FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331 AUTH.NAME AUTHOR AFFILIATION

GULDEMOND, W.G. Region 3, Ofc of the Director

RECIP.NAME RÉCIPIENT AFFILIATION LIU, L. Iowa Electric Light & Power Co.

ī

SUBJECT: Forwards Safety Insp Rept 50-331/88-06 on 880301-0415. Violation noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR  $\frac{1}{2}$  ENCL  $\frac{1}{2}$  SIZE:  $\frac{2+16}{2}$  TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

NSIC

	RECIPIENT ID CODE/NAME PD3-3 PD	COPII LTTR 1	ES ENCL 1	RECIPIENT ID CODE/NAME HALL,J.R.	COP: LTTR 2	IES ENCL 2
INTERNAL:	ACRS	2	2	AEOD	1	1
	DEDRO	1	1	NRR MORISSEAU, D	1	1
•	NRR/DLPQ/PEB 11	1	1	NRR/DLPQ/QAB 10	1	1
	NRR/DOEA DIR 11	1	1	NRR/DREP/EPB 10	1	1
	NRR/DREP/RPB 10	2	2	NRR/DRIS DIR 9A	1	1
	NRR/PMAS/ILRB12	1	1	OE LIBBERMAN, J	1	1
	OGC 15-B-18	1	1 €	REG FILE 02	1	1
_	RES/DRPS DIR	1	1	RGN3 FILE 01	1	1
ERNAL:	LPDR	1	1	NRC PDR	1	1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

R

L

D

S

, A

ח

S

APR 2 6 1988

Docket No. 50-331

Iowa Electric Light and Power Company ATTN: Mr. Lee Liu President and Chief Executive Officer

IE Towers P. 0. Box 351 Cedar Rapids, IA 52406

## Gentlemen:

This refers to the routine safety inspection conducted by Messrs. M. Parker and H. Peterson of this office on March 1, 1988 through April 15, 1988, of activities at the Duane Arnold Energy Center (DAEC) authorized by NRC Operating License No. DPR-49, and to the discussion of our findings with Mr. R. Hannen and others of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during this inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the inspection report. The inspection showed that action had been taken to correct the identified violation and to prevent recurrence. Our understanding of your corrective actions is described in Paragraph 5 of the enclosed inspection report. The violation meets the five criteria of 10 CFR 2, Appendix C, Section V.A. Consequently, no Notice of Violation was issued, and we have no further questions regarding this matter at this time.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely, CHARLES STORED IN W. O. O.

W. G. Guldemond, Chief Reactor Projects Branch 2

Enclosure: Inspection Report No. 50-331/88006(DRP)

See Attached Distribution

RIII

8805040405 880426 PDR ADOCK 05000331

TEO!

## Distribution

cc w/enclosure:
R. Hannen, Plant
Superintendent - Nuclear
R. Salmon, Technical Services
Superintendent
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Thomas Houvenagle, Iowa State
Commerce Commission
R. Hall, LPM