

Part 21 (PAR)

Event # 47123

Rep Org: EMERSON PROCESS MANAGEMENT	Notification Date / Time: 08/04/2011 12:18 (EDT)
Supplier: FISHER CONTROLS INTERNATIONAL	Event Date / Time: 08/04/2011 (CDT)
	Last Modification: 08/04/2011
Region: 3	Docket #:
City: MARSHALLTOWN	Agreement State: Yes
County:	License #:
State: IA	
NRC Notified by: BILL FITZGERALD	Notifications: RONALD BELLAMY R1DO
HQ Ops Officer: CHARLES TEAL	BINOY DESAI R2DO
Emergency Class: NON EMERGENCY	RICHARD SKOKOWSKI R3DO
10 CFR Section:	BOB HAGAR R4DO
21.21 UNSPECIFIED PARAGRAPH	PART 21 GROUP EMAIL

PART 21 - POSSIBLE WELD ROD CERTIFICATION ISSUES

"On March 3, 2011, an audit of one of Fisher Control's suppliers determined that weld rod certified by an ISO process (instead of ASME) might have been used for weld repair of castings intended for nuclear service. Fisher and the supplier are in the process of reviewing all orders affected by this issue and have yet to find any that used the subject non-confirming material

"Fisher expects to complete this evaluation by August 26, 2011. At this time, if the review determines that a failure to comply condition exists, Fisher will issue notification per the requirements of 10 CFR 21.21(b)."

IE 79
NRR



Fisher Controls International LLC
301 South First Ave
P.O. Box 190
Marshalltown, Iowa 50158-0190
USA
T (641) 754-3011
F (641) 754-2830

August 3, 2011

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555-0001

Subject: Possible Weld Rod Certification Issues Interim Notification

Fisher Controls is providing this interim notification per the requirements of 10CFR21.21(a).

On March 3, 2011, an audit of one of Fisher Control's suppliers determined that weld rod certified by an ISO process (instead of ASME) might have been used for weld repair of castings intended for nuclear service. Fisher and the supplier are in the process of reviewing all orders affected by this issue and have yet to find any that used the subject non-conforming material.

Fisher expects to complete this evaluation by August 26, 2011. At that time, if the review determines that a failure to comply condition exists, Fisher will issue a notification per the requirements of 10CFR21.21(b)

A handwritten signature in black ink, appearing to read 'Bill Fitzgerald', written over a horizontal line.

Bill Fitzgerald
Vice President, Nuclear Business Unit
Emerson Process Management, Fisher Valve Division

