# ACCELERATED

• • • • •

### REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SYSTEM

DISTRIBUTION DEMONSTRATION

ACCESSION NBR:8812290246 DOC.DATE: 88/11/30 NOTARIZED: NO DOCKET FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 050003 AUTH.NAME AUTHOR AFFILIATION MILLER,L. Iowa Electric Light & Power Co.	
HANNEN,R.L. IOWA Electric Light & Power Co. RECIP.NAME RECIPIENT AFFILIATION	R
SUBJECT: Monthly operating rept for Nov 1988 for Duane Arnold Energy Ctr.W/881215 ltr.	I
DISTRIBUTION CODE: IE24D COPIES RECEIVED:LTR / ENCL / SIZE:	D
TITLE: Monthly operating Report (per Tech Specs)	S
NOTES:	/
RECIPIENT COPIES RECIPIENT COPIES ID CODE/NAME LTTR ENCL ID CODE/NAME LTTR ENCL	•
PD3-3 LA 1 0 PD3-3 PD 5 5 HALL,J.R. 1 0	D

			-				
INTERNAL	: ACRS	10	10	AEOD/DOA	1	1	
	AEOD/DSP/TPAB	1	1	ARM TECH ADV	2	2	
	NRR/DLPQ/PEB 11	1	1	NRR/DOEA/EAB 11	1	1	
	NRR/DREP/RPB 10 REG FILE 01	1	1	NUDOCS-ABSTRACT	.1	1	
C	REG FILE 01	1 .	1	RGN3	1	1	
•	3		·	•			
EXTERNAL	: EG&G SIMPSON,F	1	1	EG&G WILLIAMS,S	1	1	
	LPDR	1	1	NRC PDR	1	1	
	NSIC	1	1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 32 ENCL 30

D

S

R

I

D

S

A

D

D

S

#### OPERATING DATA REPORT

	DOCKET NG. <u>050-0331</u> DATE <u>12-15-68</u> COMPLETED BY <u>Lonnie Hill</u> TELEPHONE <u>(319) 851-7</u>	
OPERATING STATUS	Notes	••••••••••••••••••••••••••••••••••••••
1. Unit Name: <u>Duane Arnold Energy Center</u>	_	
2. Reporting Period: <u>November 1988</u>		
3. Licensed Thermal Power (MMt): <u>1658</u>	_	
4. Nameplate Rating (Gross MMe): <u>565 (Turbine)</u>	- ·	
5. Design Electrical Rating (Nat MMe): 538	_	
6. Maximum Dependable Capacity (Gross MMe):	_	
7. Naximum Dependable Capacity (Nat HNe): 538	-	
8. If Changes Occur in Capacity Ratings (Items Number 3	through 7) Since	
the Last Report, Give Reasons: <u>N/A</u>		

9. Power Level to Which Restricted, If Any (Nat MMe): <u>Reactor shutdown for refueling/maintenance.</u> 10. Reasons for Restrictions, If Any: <u>Reactor shutdown for refueling/maintenance.</u>

	This Month	Yr-to-Date	Cumulative
11. Hours in Reporting Period	720.0	8040.0	121248.0
12. Number of Hours Reactor Nas Critical	0.0	6437.D	86776.0
13. Reactor Reserve Shutdown Hours	0	0	192.8
14. Hours Generator On-Line	0.0_	6386.2	84641.6
15. Unit Reserve Shutdown Hours	0	0	0
16. Gross Thermal Energy Generated (MMH)	0.0	10002352.2	110039668.6
17. Gross Electrical Energy Generated (MMH)	0.D	3372398.0	36932226.0
18. Net Electrical Energy Generated (MMH)	0.0	3177895.3	34623286.9
19. Unit Service Factor	0.0	79.4	69.8
20. Unit Availability Factor	0.0	79.4	69.8
21. Unit Capacity Factor (Using MDC Nat)	0.0	73.5	53.1
22. Unit Capacity Factor (Using DER Nat)	0.0	73.5	53.1
23. Unit Forced Outage Rate	0.0	1.0	14.4

 Shutdowns Scheduled Over Naxt 6 Months (Type, Date, and Duration of each; <u>Present Refueling Outage started September 29, 1988.</u>

25. If Shutdown at End of Report Period, Est. Date of Startup: December 18, 1988

-----

50 8812290246 881215 PDR ADOCK 05000331 PDC

-

.

.19/77)


### AVERAGE DAILY UNIT POHER LEVEL

DOCKET NO.	
DATE	12-15-88
TELEPHONE	Lonnie Miller (319) 851-7204

HONTH	November 1988
DAY	AVERAGE DAILY POHER LEVEL
	(MNe-Not)
1	0
2	0
3	0
4	0
5	0
6	0
7	0
8	0
9	0
10	0
11	0
12	0
13	0
14	0
15	0

DAY AVERAGE DAILY POHER LEVEL

(MNe-Net)



=

. .

~

## UNIT SHUTDOWNS AND POWER REDUCTIONS

Docket No.: 050-0331 Unit: Duane Arnold Energy Center Date: 12-15-88 Completed By: Lonnie Miller

REPORT MONTH: November 1988

Telephone: (319) 851-7204

No .	Date	Type(l)	Duration (Hours)	Reason(2)	Method of Shutting (3) Down Reactor	Licensee Event Report #	System Code (4)	Comp. Code (5)	Cause
1	11-01-88	S	720	с	4	NZA	N/A	N/A	Refueling.
		Ŀ							
								i I I	1
					·				

1 - F: Forced S: Scheduled

2 - Reason:

1

1

- A-Equipment Failure (Explain)
  - B-Maintenance or Test
  - C-Refueling
  - D-Regulatory Restriction
- ||E-Operator Training & License Examination
- F-Administrative
- G-Operational Error (Explain) H-Other (Explain)

- 3 Method
  - l-Manual 2-Manual Scram 3-Automatic Scram 4-Continued 5-Reduced Load 9-Other (Explain)
- 4 Exhibit G-Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)
- 5 Exhibit 1-Same Source

(9/77)

## MAJOR/SAFETY RELATED MAINTENANCE

i.

Т

Docket No.: 050-0331 Unit: Duane Arnold Energy Center Date: 12-15-88 Completed By: Lonnie Miller Telephone: (319) 851-7204

DATE	SYSTEM	COMPONENT	DESCRIPTION
11/13/88	Condensate	"B" Condensate Pump	Completed installation.
11/21/88	Reactor	Reactor Core	Completed core reload.
11/25/88	Residual Heat Removal	"B" Side Pump Motors	Completed installation of "B" and "D" RHR pump motors.
11/28/88	Control Rod Drive	Insert/Withdraw Lines	  Identified indications of transgranular  stress corrosion cracking in CRD insert/  withdraw lises (!Stream of the construction of the construct
11/29/88	Generator	Isophase Bus Duct Bushings	Withdraw lines. (LER 88-19 being prepared) Completed replacement of three isophase bus duct bushings.
	W i		
ļ	1	•	
	· · · ·		
	1 (	· · · · ·	
	· 1		
j			
	1.		
	ii		
	'		•

### REFUELING INFORMATION

DOCKET NO.	
COMPLETED BY	12-15-88 Lonnie Miller
TELEPHONE	(319) 851-7204

-----

#### 1. Name of facility.

- a. Duane Arnold Energy Center
- 2. Scheduled date for next refueling shutdown.
  - a. March, 1990
- 3. Scheduled date for restart following refueling.
  - a. December 18, 1988
- Will refueling or resumption of operation thereafter require a technical specification change or other license amendment? No

NRC has issued all necessary amendments.

- 5. Scheduled date(s) for submitting proposed licensing action and supporting information.
- 6. Important licensing considerations associated with refueling, e.g., new or different fuel design or supplier, unreviewed design or performance analysis methods, significant changes in fuel design, new operating procedures. None
- 7. The number of fuel assemblies (a) in the core and (b) in the spent fuel storage pool.

a. 368 b. 944

8. The present licensed spent fuel pool storage capacity and the size of any increase in licensed storage capacity that has been requested or is planned, in number of fuel assemblies.

a. 2050

 The projected date of the last refueling thet can be discharged to the spent fuel pool assuming the present licensed capacity.

' - ' -

a. 1998

#### NARRATIVE SUMMARY OF OPERATING EXPERIENCE

DOCKET NO.	050-0331
	12-15-88
	Lonnie Miller
TELEPHONE	(319) 851-7204

10-01-88 At the beginning of the month the Duane Arnold Energy Center was shutdown for rafueling. There were 2 reportabla events during the month.

11-06-88

At 1720 hours the plant was shutdown for the Cycle 9/10 refuel outage when a Primary Containment Isolation System (PCIS) half Group III ("B" side) isolation was received. Investigation of the trip revealed that it had occurred due to a trip of the "B" Reactor Protection System (RPS) motor-generator (NG) sat.

The cause for the RPS NG set trip was failure of a noreally energized relay (Generel Electric CR120A) in the MG set control circuitry. The cause of the relay failure was its contact retainer. This ratainer was of a type susceptible to ignition from the heat produced by the relay. The day before the relay failure the MG set was load tested under various load conditions. It is suspected that additional ambient heat produced under high load conditions may have contributed to the relay failure.

Immediate corrective actions following the trip of the MG set were to switch the "B" RPS bus to alternate power supply and verify automatic function for the Group III isolation. Following verification, tha Group III isclation was reset. To repair tha MG set, a new relay with a contact retainer which is not susceptible to ignition from relay heat was installed.

This event had no effect on the safe operation of the plant.

#### LER 88-17

10-18-88

ہے۔

At 1328 hours tha plant was shutdown for the Cycle 9/10 refuml outage when a full Reactor Protection System trip and Group I through V isolation signals were received. Investigation determined that the event occurred due to a trip of a "B" Reactor Protection System (RPS) Notor-Generator (NG) set Electrical Protection Assemby (EPA) breaker concurrent with a surveillance test in progress. It is suspected that a spurious signal within the EPA caused the EPA breaker to trip.

Following the EPA breaker trip, the "B" RPS bus was repowered by the alternate power supply. Group V (Reactor Watar Cleanup) isolatien valves and Secondary Containment isolation dampers isolated as a result of the trip. Various other Primary Containment system valves and breakers were out of service for maintenance at the time of the evont and the Control Rod Drives were isolated. Primary Containment was not required at the time of tha trip. This event had no effect on the safe operation of the plant, nor would it have an effect on safe operation during any other plant conditions.

LER 88-18

-

### Iowa Electric Light and Power Company

December 15, 1988 DAEC-88-0919

Mr. A. Bert Davis Regional Administrator Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

> Subject: Duane Arnold Energy Center Docket No: 50-331 Op. License DPR-49 November 1988 Monthly Operating Report

Dear Sirs:

Please find enclosed the Duane Arnold Energy Center Monthly Operating Report for November, 1988. The report has been prepared in accordance with the guidelines of Regulatory Guide 1.16 and distribution has been made in accordance with DAEC Technical Specifications, Section 6.11.1.c.

Very truly yours,

) 12-15-88

Rick L. Hannen Plant Superintendent - Nuclear

RLH/LDM/go Enclosures File A-118d

cc: U. S. NRC ATTN: Document Control Desk Washington, D. C. 20555

> Mr. J. R. Hall Project Manager 1 Whiteflint North Mail Stop 13E21 11555 Rockville Pike Rockvil<del>le</del>, MD 20852

INPO Records Center 1100 Circle 75 Parkway Atlanta, GA 30339 Mr. Phillip Ross U.S. NRC Maryland Nation Bank Building Washington, D.C. 20555 (2)

NRC Resident Inspector

Mr. Dennis Murdock Central Iowa Power Cooperative Box 2517 Cedar Rapids, IA 52406

Mr. Russ Gamble Corn Belt Power Cooperative 1300 13th Street North Humboldt, IA 50548