



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

Mr. Duane Arnold
President
Iowa Electric Light & Power Company
P. O. Box 351
Cedar Rapids, Iowa 52406

Mr. Robert Lowenstein, Esquire
Harold F. Reis, Esquire
Lowenstein, Newman, Reis and Axelrad
1025 Connecticut Avenue, N. W.
Washington, D. C. 20036

Cedar Rapids Public Library
426 Third Avenue, S. E.
Cedar Rapids, Iowa 52401

Docket File
NRC PDR
Local PDR
NRR Rdg
ORB#3 Rdg
H. Denton
E. Case
V. Stello
D. Eisenhut
B. Grimes
R. Vollmer
T. Ippolito
R. Reid
V. Noonan

G. Knighton
A. Schwencer
D. Ziemann
P. Check
G. Lainas
D. Davis
OELD
OI&E (3)
S. Sheppard
Project Manager
ACRS (16)
NRC Participants
TERA
J. Buchanan

7903150416

Docket
50-331

FEB 15 1979

MEMORANDUM FOR: Brian K. Grimes, Assistant Director for Engineering and Projects

FROM: Thomas A. Ippolito, Chief, Operating Reactors Branch #3

SUBJECT: SUMMARY OF DISCUSSION WITH IOWA ELECTRIC

The DOR staff met with representatives of Iowa Electric on February 13, 1979 to discuss the information needed for staff review and evaluation of (1) the suitability of safe-end repair welds and (2) the removal and consequences of shield lead plug and carbon steel fragments in the primary system of the Duane Arnold Energy Center. The list of attendees is provided in Enclosure 1.

With regard to the repair welds, the staff stated that it needed information and supporting analysis on the following subjects:

1. Fatigue (thermal and mechanical)
2. Stress Corrosion
 - a. Significance of any weld defects or crevices (stress analyses assuming indications are crevices)
 - b. Potential for excessive internal reinforcement
 - c. Sugaring effects
3. Potential of propagation if cracks are initiated
4. Augmented inservice inspection proposal
5. Improvements in leak detection sensitivity and decision/action criteria

The information and analysis required by the staff for their review of potential loose parts is as follows:

1. Potential for core flow blockage or other safety implications
2. Methods for determining the existence of lead contamination in the primary systems

M4
6D

OFFICE ➤
SURNAME ➤
DATE ➤

Brian K. Grimes

- 2 -

FEB 15 1979

3. If contamination exists, the methods for removal and analysis of potential effects on primary system materials, particularly Inconel.

A technical meeting covering this item was scheduled for February 20,* 1979.

Original Signed by
T. A. Ippolito

Thomas A. Ippolito, Chief
Operating Reactors Branch #3
Division of Operating Reactors

Enclosure:
Attendance List

*Meeting was subsequently changed
to February 21, 1979.

DISTRIBUTION:

Docket 50-331
ORB-3 Reading
NRR Reading
NRC PDR
LOCAL PDR
VStello
DEisenhut
RVollmer
VNoonan
TAIppolito
RClark
SSheppard
EJordan
FCoffman

OFFICE	DOOR-ORB-3					
SURNAME	T.A.Ippolito:esp					
DATE	2/15/79					

ENCLOSURE

FEB 15 1979

LIST OF ATTENDEES

IOWA ELECTRIC

S. Tuthill
L. Liu
L. Root
R. Lowenstein

NRC - STAFF

V. Stello
D. Eisenhut
B. Grimes
V. Noonan
T. Ippolito
F. Coffman (Part-time)

OFFICE ➤						
SURNAME ➤						
DATE ➤						