PMSTPCOL PEmails

From: Foster, Rocky

Sent: Tuesday, August 02, 2011 6:28 AM

To: Chappell, Coley; wemookhoek@stpegs.com; Head, Scott; jeprice@stpegs.com; Agles,

James; Tai, Tom; Chakrabarti, Samir

Cc: Abeywickrama, Bernadette; Wunder, George; STPCOL

Subject: NINA OI Meeting Agenda for August 3, 2011

Attachments: OI List 8-03-11.pdf; BNL Initial Feedback 06-23-11 RAI Responses - Updated on

072911.docx

Good Morning,

NOTE to Bernie: Please enter the Open Items Master List file (OI List_8-3-11.pdf) into ADAMS and provide the ADAMS accession number to Cheri Nagel and myself so as to be included in the meeting summary for August 3, 2011.

The Open Items telecom is schedule for August 3, 2011. The morning session is from 09:00 am to 11:00 am and the Chapter 3 afternoon session is from 2:00 pm to 4:00 pm.

The bridge line call-in information for the morning session and agenda topics are as follows:

This is a standing bridge line available every Wednesday from 09:00 am to 11:00 am through December 28, 2011.

Conference Line - 888-455-2563

Pass Code - 84624

09:00 am - 11:00 am Agenda:

- NRC/NINA Continuation of Chapter 9 fuel rack structural review RAI responses discussion (09.01.02-6, 09.01.02-7 & 09.01.02-9)
- NRC/NINA OI Master List (attached)
- Comments/Questions

For the August 3, 2011, Wednesday afternoon call, Tom Tai would like to start at 2:00 pm with EMB2, followed by SEB2 at 3:00 pm such that it is easier for the SEB2 consultants from CA to participate with the following agenda items:

For those who want to participate on this call but are outside the office:

Conference Line - 866-803-2146

Pass Code - 7482641

From 2:00 pm to 3:00 pm:

- 1. RAI 5952 Ch 3.9.1 ACSTIC2 audit questions.
- 2. RAI 5870 Ch 3.9.4 ASME spec
- 3. Ch 3.9.2 questions
- 4. Ch 3.7/3.8 punch-list status

From 3:00 pm to 4:00 pm:

- 5. RAI 5919 II/I
- 6. NRC feedback on MSM vs. SM confirmatory analysis
- 7. NINA's clarification on Letter 110099 response (03.08.04-30, Table 3H6-6)
- 8. NINA's clarification on hurricane (Peter Arnold's question from last week)
- 9. Miscellaneous items

Thanks,

Rocky D. Foster
Project Manager
US Nuclear Regulatory Commission
Office of New Reactors
Division of New Reactor Licensing
BWR Projects Branch (NGE)
Mai Stop T6D38M
(301) 415-5787
rocky.foster@nrc.gov

Hearing Identifier: SouthTexas34Public_EX

Email Number: 2998

Mail Envelope Properties (26E42474DB238C408C94990815A02F096008A7404A)

Subject: NINA OI Meeting Agenda for August 3, 2011

Sent Date: 8/2/2011 6:28:16 AM **Received Date:** 8/2/2011 6:28:18 AM

From: Foster, Rocky

Created By: Rocky.Foster@nrc.gov

Recipients:

"Abeywickrama, Bernadette" < Bernadette. Abeywickrama@nrc.gov>

Tracking Status: None

"Wunder, George" < George. Wunder@nrc.gov>

Tracking Status: None

"STPCOL" <STP.COL@nrc.gov>

Tracking Status: None

"Chappell, Coley" <ccchappell@STPEGS.COM>

Tracking Status: None

"wemookhoek@stpegs.com" <wemookhoek@stpegs.com>

Tracking Status: None

"Head, Scott" <smhead@STPEGS.COM>

Tracking Status: None

"jeprice@stpegs.com" <jeprice@stpegs.com>

Tracking Status: None

"Agles, James" <jaagles@STPEGS.COM>

Tracking Status: None

"Tai, Tom" <Tom.Tai@nrc.gov>

Tracking Status: None

"Chakrabarti, Samir" <Samir.Chakrabarti@nrc.gov>

Tracking Status: None

Post Office: HQCLSTR01.nrc.gov

 Files
 Size
 Date & Time

 MESSAGE
 2177
 8/2/2011 6:28:18 AM

OI List 8-03-11.pdf 270421

BNL Initial Feedback 06-23-11 RAI Responses - Updated on 072911.docx 25867

Options

Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal

Expiration Date: Recipients Received:

2011 NINA/STP COLA Item Status Counts

OPEN	01/12/2011	01/19/2011	01/26/2011	02/09/2011	02/16/2011	02/23/2011	03/04/2011
NRC action	45	34	37	34	31	36	22
STP action	20	25	22	22	20	28	37
	65	59	59	56	51	64	59
CONFIRMATORY	01/12/2011	01/19/2011	01/26/2011	02/09/2011	02/16/2011	02/23/2011	03/04/2011
NRC action	2	2	2	2	2	2	2
STP Action	81	138	154	152	154	155	147
	83	140	156	154	156	157	149
CLOSED	01/12/2011	01/19/2011	01/26/2011	02/09/2011	02/16/2011	02/23/2011	03/04/2011
	53	92	92	95	101	101	116
OPEN	03/10/2011	03/16/2011	03/23/2011	03/30/2011	04/06/2011	04/13/2011	04/20/2011
NRC action	52	31	31	35	38	37	35
STP action	13	25	24	22	20	17	17
	65	56	55	57	58	54	52
CONFIRMATORY	03/10/2011	03/16/2011	03/23/2011	03/30/2011	04/13/2011	04/13/2011	04/20/2011
NRC action	2	2	2	2	2	2	2
STP Action	82	83	84	84	84	84	86
	84	85	86	86	86	86	88
CLOSED	03/10/2011	03/16/2011	03/23/2011	03/30/2011	04/06/2011	04/13/2011	04/20/2011
	116	118	118	118	118	122	124
OPEN	04/27/2011	05/04/2011	05/11/2011	05/18/2011	05/25/2011	06/01/2011	06/08/2011
NRC action	28	29	6	6	11	11	11
STP action	24	23	8	16	11	11	11
	52	52	14	22	22	22	22
CONFIRMATORY	04/27/2011	05/04/2011	05/11/2011	05/18/2011	05/25/2011	06/01/2011	06/08/2011
NRC action	2	2	2	2	2	2	2
STP Action	86	90	95	95	95	96	96
	88	92	97	97	97	98	98
CLOSED	04/27/2011	05/04/2011	05/11/2011	05/18/2011	05/25/2011	06/01/2011	06/08/2011
	124	124	124	124	124	124	124
OPEN	06/15/2011	06/22/2011	06/29/2011	07/06/2011	07/13/2011	07/20/2011	07/27/2011
NRC action	11	11	11	11	19	19	19
STP action	11	11	11	11	6	8	8
	22	22	22	22	25	27	27
CONFIRMATORY	06/15/2011	06/22/2011	06/29/2011	07/06/2011	07/13/2011	07/20/2011	07/27/2011
NRC action	2	2	2	2	2	2	2
STP action	96	96	96	96	96	96	96
	98	98	98		98	98	98
CLOSED	06/15/2011			07/06/2011		07/20/2011	07/27/2011
	124	124	124	124	125	125	125

2011 NINA/STP COLA Item Status Counts

OPEN	08/03/2011	08/10/2011	08/17/2011	08/24/2011	08/31/2011	
NRC action	20	, .,	, ,,====	, ,	, , , _ , _ ,	
STP action	7					
orr detroit	27					
CONFIRMATORY	08/03/2011	08/10/2011	08/17/2011	08/24/2011	08/31/2011	
NRC action	2	00, 10, 2011	00/1//2011	00,24,2011	00,31,2011	
STP Action	96					
311 Action	98					
CLOSED	08/03/2011	08/10/2011	08/17/2011	08/24/2011	08/31/2011	
CLOSED	125	08/10/2011	08/17/2011	08/24/2011	08/31/2011	
	123					

2011 NINA/STP COLA Item Status Counts

	\dashv
-	\dashv
-	
	\dashv
	-
	\dashv
-	\dashv

STP Phase 4 Open Items

atus							tory		tory	tory	tory	tory
OI Status	oben	obeu	uedo	uedo	oben	Closed	confirmatory	Open	confirmatory	confirmatory	confirmatory	confirmatory
ပိ	End of P4 open	09/30/2011 open	08/31/2011 open									
Ol Closure Date						07/07/2011						
Next Action Completion Date	3rd Quarter 2011 and 8/19/2011	08/24/2011	08/14/2011			07/07/2011		08/30/2011	08/30/2011	08/30/2011	08/30/2011	08/30/2011
Next Action	NRC - exemption issuance (depends on completion of all other SER chapters and FEIS)(STP-Submitted site-specific departure on New Fuel Rack on 7/19/11)	STP - RAI #379 (5856) issued on 7/13/2011. NRC - Ongoing Review of Rev 5 (STP-Proposed revision to COL Part 1 submitted on 6/23/11)	NRC - to review 4/6/11 completed map tables for Part 70 license and 4/5/11 Parts 30, 40 license withdrawl (STP-Submitted changes to COL on Part 70 on 7/14/2011)	STP/NRC	NINA - provide adequate V&V package for ACSTIC2	NRC - to review latest responses to RAI 5058 in 5/16/11	NINA - include proposed FSAR changes in letter 110064 (4/13/2011) in next FSAR revision.	9 2010 audit of NRC - to review latest response to 3.09.02-igy and license 44 on 6/30/11	NRC - to review responses to 3.09.02-45 on 2/28/11, and responses to RAI 5256 and 03.09.02-49 on 6/30/11	NRC - to review responses to 3.09.02-46 on 2/28/11, and responses to RAI 5256 and 03.09.02-49 on 6/30/11	NRC - to review responses to 3.09.02-47 on 2/28/11, and responses to RAI 5256 and 03.09.02-49 on 6/30/11	NRC - to review responses to 3.09.02-48 on 2/28/11, and responses to RAI 5256 and 03.09.02-49 on 6/30/11
Description	Tier 1 Departure exemptions	Financial Qualifications	Parts 30, 40 and 70	3.7 and 3.8 Open Items and RAIs being handled by Tom Tai during weekly breakout calls	ACSTIC2 V&V	Questions from the August 23-25, 2010 audit of WEC, SWE, Toshiba, and XGEN analyses	ACSTIC2 FSAR markup	Questions from the October 18-19 2010 audit of NRC - to revie CVAP, including ACM methodology and license 44 on 6/30/11 condition	Table 5.4 of FIV Stress Analysis Report of the Control Rod Guide Tube and Control Rod Drive Housing	Tables 5.11 and 5.13 of FIV Stress Analysis Report of the High Pressure Core Flood Sparger and Coupling	Stress Analysis Report of	STP steam dryer modal analysis and Japanese hammer test results
RAI#	n/a	n/a	3944 01-15	3.7 and 3.8 RAIs	03.09.01-1	3 3.09.02-16 03.09.02-16 to -43 (5058)	3 03.09.02-21 03.09.02-21 (5058)	3.09.02-44 03.09.02-44 (5256)	3 3.09.02-45 03.09.02-45 (5343)	3 3.09.02-46 03.09.02-46 (5343)	3 3.09.02-47 03.09.02-47 5343	3 3.09.02-48 03.09.02-48 5343
# 10	1-1	1-5	1-6	3 3.7 and 3.8	3 03.09-01-1 03.09.01-1	3.09.02-16	03.09.02-21	3 3.09.02-44	3.09.02-45	3.09.02-46	3.09.02-47	3.09.02-48
Chp Item #	-	υ —	6	39	(F)	40 3	(C)	41 3	42 3	43 3	44 3	45 3
Ite												

STP Phase 4 Open Items

SER OI Status Completion Date	uedo	confirmatory	oben	uedo	oben		obeu	oben	uedo uedo	oben open
Ol Closure Date	-			-						
Next Action Completion Date	08/30/2011	08/30/2011		09/15/2011	07/29/2011		07/29/2011	07/29/2011	09/01/2011	09/01/2011
Next Action	NRC - Review of revised technical reports submitted by STP on 6/30/11 to support review of FIV program (RAI 03.09.02-49 revised submittal on 6/30/11)	NRC - to review responses to 3.09.02-50 on 2/28/11, and responses to RAI 5256 and 03.09.02-49 on 6/30/11	NINA - respond to RAI 5870	STP - Supplemental RAI responses w/ final revision by 9/15/2011	NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response on Gaps & Tolerances topic on 9/15/11)		NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response on NFR/SFR forces and stresses topic on 9/15/11)	NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response on NFR/SFR forces and stresses topic on 9/15/11) NRC - Review of RAI responses submitted on 8/01/11	NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response on NFR/SFR forces and stresses topic on 9/15/11) NRC - Review of RAI responses submitted on 8/01/11 NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response items: c, g, I, j, m and n on 9/15/11)	NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response on NFR/SFR forces and stresses topic on 9/15/11) NRC - Review of RAI responses submitted on 8/01/11 NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response items: c, g, I, j, m and n on 9/15/11) NRC - Review of RAI responses submitted on 6/23/11 (STP - Submit RAI response items: b, c, d and e on 9/15/11)
Description	Sample pressure spectra on the sub-scale steam dryer	Sub-scale dryer pressure spectra compared to Japanese ABWR	FMCRD spec load requirements	Basis for WCAP 17311 and 17331: Fuel rack structural analysis	Descriptions of pools, racks and fuel-handling system		Fuel rack loads and load combinations		d load combinations	d load combinations nodeling and analysis
RA#	3 3.09.02-49 03.09.02-49 (5343) S	3 3.09.02-50 03.09.02-50 (5343) S	03.09.04-1 (5870) F	4561 (ltr 329), B 09.01.01-4 RAI si 5685 (ltr 377) issued with 8 supplemental questions	5685 (ltr 377) , D		5685 (ltr 377), 09.01.02-3			
# IO C	3 3.09.02-49	3 3.09.02-50	3 03.09.04-1	9.1.14	9 tpq		9 tbd			
Chi		3		86	66	_			101 102 6	

STP Phase 4 Open Items

OI Status	uedo	uado	oben	open
SER Completion Date				
OI Closure Date				
Next Action Completion Date	09/15/2011	07/29/2011	08/15/2011	08/15/2011
Next Action	STP - RAI response on 9/15/2011	NRC - Review of RAI responses submitted on 6/23/11	NRC - Review 3/31/11 response and supporting white paper submitted on 6/15/11. Staff review extended to 8/15/11.	NRC - Review 3/31/11 response and supporting white paper submitted on 6/15/11. Staff review extended to 8/15/11.
Description	Fuel rack thermal stress analysis	Fuel rack seismic loading	Site Psecific ITAAC and Tier 1 exemption for 99% charcoal filter efficiency	Standard or Site Specific departure regarding charcoal efficiency design change
RAI#	5685 (ltr 377), 09.01.02-8	5685 (ltr 377), 09.01.02-9	5540 (ltr 375), 09.04.03-2	5540 (ltr 375), 09,04.03-3
Chp OI#	9 tpd	9 tpq	6 tpd	9 tbd
Cr Item #	105	106	109	110

STP New and Spent Fuel Racks

RAI Responses Submitted 06/23/2011

Preliminary Review Comments/Requested Clarifications

(Prepared by R. Morante, X. Wei, BNL, 07/18/2011)

(Updated by R. Morante, X. Wei, BNL, 07/29/2011)

On 06/23/2011, STP (the applicant) submitted responses to some of the staff's nine (9) RAIs submitted to the applicant on 05/09/2011. The applicant responded in accordance with the response schedule it had earlier submitted to the staff, with one (1) departure. The response to RAI 09.01.02-8 had been scheduled for 06/23/2011. In the applicant's 06/23/2011 response letter, the applicant deferred the response to RAI 09.01.02-8 until 09/15/2011.

Preliminary comments and requests for clarifications, related to the responses submitted, are noted below. Acceptance of a clarification does NOT constitute acceptance of the associated RAI response.

RAI 09.01.02-2 [NOTE: Response to part b. due on 09/15/2011.]

- (1) Clarification for Sketch 7 was provided during telecom on 07/13/2011. (The two small vertical lines in the cell walls in Sketch 7 denote continuous butt welds to join the two pieces of channel cell walls together)
- (2) Height of the leveling pad was discussed during telecom on 07/13/2011. STP will provide the height. (Sketch 6, leveling Pad & Screw; the height of the leveling pad is 1.9")
- (3) Clarification of welding of tie joints to the corners of adjacent cells on Sketch 14 was provided during telecom on 07/13/2011. (The cell to cell welds are on one (either) side of the tie bar (joint). The tie bar (joint) is tapered to fit in the spacing between adjacent cells. Eccentricity of the welds is not considered in the calculation because it is small.)
- (4) Clarify the following related to Sketch 13:
 - a. What is the material type of the 1/2" plates? How will they be attached to the rack? (The 1/2" plates will be ASTM A240, TP304L. It is a continuous plate wrapping around the rack. It will be welded to the rack by 0.12" fillet welds, 4" long, on each cell, plate to be welded top & bottom, clarification to be provided in the WCAP update on 9/15/11)
 - b. Have the loads from the linkage been considered in the fuel rack design? Are those loads treated as concentrated loads on cell walls? (Not done yet, due 9/15/11) c. Have the design checks on the 1/2" plates and linkage been done? (Not done yet, due 9/15/11)

RAI 09.01.02-3 [NOTE: Response to part a. due on 09/15/2011.]

(1) Clarification needed for the stuck fuel assembly calculation. Explain the basis for the assumptions used in calculating the axial forces that resist the moment at the bottom of the rack, caused by the horizontal force at the top of the rack. (The calculation of the welding stress due to the axial forces that resist the moment is based on the assumptions that 1) two adjacent cells resist the entire moment at the base (a conservative assumption); 2) the axial force is applied uniformly on the four sides of the cell-to-baseplate welds to simplify the calculation, since the first assumption is conservative. The staff did a simple hand calculation considering a trianglular stress distribution across the bottom of 2 adjacent cells. The results show that the maximum stress in the weld exceeds the allowable stress by 4%. Considering the conservative assumption noted in (1) above, the staff concludes that the stuck fuel assembly calculation is acceptable and the cell-to-baseplate weld is strong enough to resist the stuck fuel assembly loads.)

RAI 09.01.02-4 [NOTE: STP provided response to NRC on 08/01/2011.]

RAI 09.01.02-5 [NOTE: Responses to parts c., g., j., k., m., n. due on 09/15/2011.]

- (1) What criteria does ANSYS apply for "bi-section" of the input time step to a 0.0001 sec. time step. Did this occur in the analyses performed? (Clarified. The criterion is convergence failure after 25 iterations. This did not occur in the STP spent fuel storage rack analyses. Satisfactory explanation.)
- (2) Clarify Figure 8. The location of weld zones and sizes and locations of support plates shown in Figure 8 are inconsistent with the information provided in other locations of the RAI response document. For example, Figure 8 shows 8 grid weld locations and 12 support locations with same size support plates, while Sketch 14 of RAI response to RAI 09.01.02-2 shows 4-12" fillet welds for cell to cell weld, Sketch 16 of RAI response to RAI 09.01.02-2 shows 8 support plates with two sizes. (Clarified. Information in the figures reflect the analysis model; this is superseded by the information in the sketches. The latest design information will be used in the updated analysis and documented in the 9/15/11 update to the Technical Report.)
- (3) On Figure 10, is the "1/2" base plate" a typo? Should be 1-1/2" base plate? (Clarified. To be fixed in the 9/15/11 update to the Technical Report.)
- (4) How are the large support plate and leveling pad modeled? Figures 8 through 10 only show the small support plate and leveling screw. (Clarified. The leveling pad is not modeled explicitly, only the leveling screw is modeled. The size of the leveling pad will be taken into account in detailed hand calculations for loading on the spent fuel pool floor. The revised support plate configuration will be documented in the 9/15/11 update to the Technical Report.)

RAI 09.01.02-6 [NOTE: Responses to parts b., c., d., e. due on 09/15/2011.]

(1) Clarify Cell-Cell weld calculation: The leg length of 0.12 inches used in the calculation is inconsistent with the 0.08 inches shown in Sketch 14 of the response to RAI 09.01.02-2. (Clarified. The correct leg length of the cell-cell weld is 0.08". The leg length is

- reduced because of the increase of weld length. Correct information will be in the 9/15/11 update to the Technical Report.)
- (2) In response to Item a, Level D allowable stress calculation, the value of Su used, 68 ksi, is the value at 140 °F, according to Table 4-2 of the spent fuel rack Technical Report. The value at 212 °F should be used. (Clarified. Data for 212 °F will be used in the 9/15/11 update to the Technical Report.)
- (3) In response to Item a, Cover plate Weld, it states that "The cover plate weld is evaluated over a length of 5 inches, even though it is a continuous fillet weld." This statement is inconsistent with Sketches 9 through 11 of response to RAI 09.01.02-2, which shows 4-15" fillet weld for cover plate weld. (Clarified. The weld sizes have been changed to 4" long on 15" center. STP will re-analyze and include in the 9/15/11 update to the Technical Report. An RAI response revision was recommended by the staff, because of the significance of the change. Applicant considering this.)

 Also, explain whether a finer element mesh, comparable to the element mesh for cell to cell weld, is used for cover plate weld. (Discussed. Staff not clear about the answer. Need to discuss again.)

RAI 09.01.02-7

- (1) The staff acknowledges that spent fuel storage racks are not included in the RG 1.26 Quality Group classifications. However, as noted in FSAR Section 9.1.2.1.3, the spent fuel racks are Seismic Category I, in accordance with RG 1.29. As such, all of the QA provisions of 10 CFR 50 Appendix B would appear to be applicable. Clarify what aspects of Appendix B are deemed to be not applicable to spent fuel storages racks, and the basis for this determination. (Applicant stated that a similar question had been asked and answered during the original DCD review. According to the applicant, the response to Question 210.15 indicated that the QA provisions of 10 CFR 50 Appendix B do not apply to spent fuel racks. In addition, the applicant stated that RG 1.29 provides relief from App. B for certain conditions, which the applicant claims apply to the spent fuel storage racks. NRC & BNL staff to review DCD Chapter 20, question 210.5, DCD Table 3.2-1, and NUREG 1503, Vol. 1, p. 3-12 [ABWR FSER]. STP to evaluate a possible revised response to provide clarification.)
- (2) The staff concurs that the regulatory requirements for periodic ISI of spent fuel storage racks originates from 10 CFR 50.65 "Maintenance Rule". RG 1.160 clarifies acceptable procedures for implementation of the Maintenance Rule, and includes special guidance specifically for structures. Clarify how the guidance provided in RG 1.160 for structures will be implemented for spent fuel storage racks. (On-going discussion. Question whether DRAP program applies. The peer review group considered Fuel Racks under the DRAP program and determined that the fuel racks not to be included as SSC. STP adopted NEI Maintenance Rule template 0702A, Revision 0, dated 3/08 such that 30 days prior to fuel load the Maintenance Rule goes into effect. STP indicated that "A" at the end designates NRC acceptance. Staff to review the FSAR and NEI Maintenance Rule template. Samir to Contact Todd Hilsmeier to

discuss requirements under the DRAP program. STP to evaluate a possible revised response to provide clarification.)

RAI 09.01.02-8 [NOTE: Response has been deferred to 09/15/2011.]

RAI 09.01.02-9

The response discusses an alternate formulation that produced synthetic time histories that do not require peak clipping and baseline correction. However, no quantitative information is provided for the alternate formulation. Eliminating the need for baseline correction and peak clipping would appear to have definite advantages. The alternate time histories may also eliminate the staff's questions (part f.) about the peculiar characteristics of the baseline-corrected displacement time histories presented in the Technical Report. These were NOT addressed in the response. Therefore,

- (1) Clarify the basis for retaining the initial synthetic time histories, even though several difficulties are overcome by the alternate formulation; and
- (2) Provide answers to the staff's questions in part f. of the RAI, including comparison to the displacement time histories obtained by the alternate formulation.

(Discussion of RAI -9 was deferred to August 3, 2011 telecom.)