PMSTPCOL PEmails

From: Tai, Tom

Sent: Monday, August 15, 2011 10:04 AM

To: Price, John E

Cc: STPCOL; Wunder, George; Chakrabarti, Samir; Chakravorty, Manas; McNally, Richard

Subject: STP - Table 3.2-1 Errata

John,

I was going through Revision 5 of Table 3.2-1 in the FSAR and noticed the following anomalies:

Sheet 3.2-5 Under P8, Ultimate Heat Sink, it includes "(See U16)"

Sheet 3.2-8, there is no system or structure U16. Instead, under U20, UHS and Associated Structures, it reads, "(See P8)".

I believe there is a typo in sheet 3.2-5, that under P8, the parenthesized note should read "U20" instead of "U16".

If and when this correction is made in sheet 3.2-8, shouldn't "Y2.2", RSW Piping Tunnel, be included in the parenthesis under U20?

Regards

Tom Tai DNRL/NRO (301) 415-8484 Tom.Tai@NRC.GOV Hearing Identifier: SouthTexas34Public_EX

Email Number: 3020

Mail Envelope Properties (0A64B42AAA8FD4418CE1EB5240A6FED13E6257DE73)

 Subject:
 STP - Table 3.2-1 Errata

 Sent Date:
 8/15/2011 10:03:33 AM

 Received Date:
 8/15/2011 10:03:35 AM

From: Tai, Tom

Created By: Tom.Tai@nrc.gov

Recipients:

"STPCOL" <STP.COL@nrc.gov>

Tracking Status: None

"Wunder, George" < George. Wunder@nrc.gov>

Tracking Status: None

"Chakrabarti, Samir" <Samir.Chakrabarti@nrc.gov>

Tracking Status: None

"Chakravorty, Manas" < Manas. Chakravorty@nrc.gov>

Tracking Status: None

"McNally, Richard" <Richard.McNally@nrc.gov>

Tracking Status: None

"Price, John E" <jeprice@STPEGS.COM>

Tracking Status: None

Post Office: HQCLSTR02.nrc.gov

Files Size Date & Time

MESSAGE 671 8/15/2011 10:03:35 AM

Options

Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal

Expiration Date: Recipients Received: