

Appendix

NOTICE OF VIOLATION

Iowa Electric Light and
Power Company

Docket No. 50-331

As a result of the inspection conducted on November 1-30, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

The Duane Arnold Energy Center Technical Specifications Section 6.8.1, states in part, "Detailed written procedures involving nuclear safety, . . . covering areas listed below shall be prepared. . . . All procedures shall be adhered to." Section 6.8.1, item 6 states, "Surveillance and testing requirements".

Contrary to the above, following surveillance testing on the scram discharge volume on November 11, 1981, the instrument line drain valve, V-18-20, was locked open. Valve 18-20 is required to be locked shut by STP BS-6 upon completion of STP BS-6. The valve was repositioned correctly on November 17, 1981.

This is a Severity Level VI violation (Supplement I).

The inspection showed that action had been taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter.

Dated _____

R. L. Spessard, Director
Division of Resident and
Project Inspection

8201210027