

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8006270267 DOC.DATE: 80/06/20 NOTARIZED: NO DOCKET #
 FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH.NAME AUTHOR AFFILIATION
 RAGER,M. Iowa Electric Light & Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-020/03L-0:on 800523,during normal surveillance testing of emergency bus time delay relays,seven Gould ITE-27D undervoltage relays found to have excessive delays. Caused by instrument drift,Relays recalibr.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: Lt 1
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	BC IPPOLITO, T 05	1	1	PM KEVERN, T. 06	2	2
INTERNAL:	A/D CORE & CS	1	1	A/D RAD PROT	1	1
	A/D REACT SYS	1	1	A/D TECHNOLOGY	1	1
	AEOD	10	10	AUX SYS BR	1	1
	CHEM ENG BR	1	1	CONT SYS BR	1	1
	CORE PERF BR	1	1	EMERG PREP	1	1
	EQUIP QUAL BR	1	1	HANAUER, S.	1	1
	I&C SYS BR	1	1	I&E 09	2	2
	JORDAN, E./IE	1	1	MOORE, V.	1	1
	MPA 11	3	3	NRC PDR 02	1	1
	OP EX EVAL BR	3	3	OR ASSESS BR	1	1
	PPAS	1	1	QA BR	1	1
	REG FILE 01	1	1	SIT ANAL BR	1	1
	SYS INTERAC BR	1	1	TERA:DOUG MAY	1	1
EXTERNAL:	ACRS	16	16	LPDR 03	1	1
	NSIC 04	1	1			

JUN 30 1980

264
 AS/II
 4
 BD

TOTAL NUMBER OF COPIES REQUIRED: LTR 61 ENCL 61