

Central Files

Iowa Electric Light and Power Company

June 13, 1980
LDR-80-160

LARRY D. ROOT
ASSISTANT VICE PRESIDENT
NUCLEAR GENERATION

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

This letter is our response to IE Bulletin No. 80-09 concerning hydramotor actuator deficiencies. As a result of our review of the Duane Arnold Energy Center, we have concluded that no hydramotor actuators as described by the bulletin are installed at our facility.

Very truly yours,

Larry D. Root

Larry D. Root
Assistant Vice President
Nuclear Generation

LDR/RFS/mz

cc: U. S. Nuclear Regulatory Commission
Director of Reactor Construction Inspection, O.I.E.
Washington, D.C. 20555

- R. Salmon
- D. Arnold
- L. Liu
- S. Tuthill
- K. Meyer
- D. Mineck
- J. Van Sickle
- T. Kevern (NRC)
- File: A-101a, BN8009

JUN 20 1980

AD/E
2

67

8007020719

8