

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8008130523 DOC.DATE: 80/08/07 NOTARIZED: NO DOCKET #  
 FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331  
 AUTH.NAME AUTHOR AFFILIATION  
 RAGER,M. Iowa Electric Light & Power Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-033/03L-0: on 800711, during normal surveillance testing, reactor core isolation cooling turbine trip throttle value would not open electrically. Caused by corroded contacts in motor operator limit switch. Contacts cleaned.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR / ENCL / SIZE: 171  
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	IPPOLITO, T.	3	3			
INTERNAL:	A/D COMP&STRUCT	1	1	A/D ENV TECH	1	1
	A/D MATL & QUAL	1	1	A/D OP REACTORS	1	1
	A/D PLANT SYS	1	1	A/D RAD PROT	1	1
	A/D SFTY ASSESS	1	1	A/D TECHNOLOGY	1	1
	ACC EVAL BR	1	1	AEOD	10	10
	AUX SYS BR	1	1	CHEM ENG BR	1	1
	CONT SYS BR	1	1	CORE PERF BR	1	1
	D/DIR, HUM FAC S	1	1	DIR, ENGINEERING	1	1
	DIR, HUM FAC SFY	1	1	DIR, SYS INTEG	1	1
	EFF TR SYS BR	1	1	EMERG PREP	1	1
	EQUIP QUAL BR	1	1	GEOSCIENCES	1	1
	HUM FACT ENG BR	1	1	HYD/GEO BR	1	1
	I&C SYS BR	1	1	I&E	09	2
	JORDAN, E./IE	1	1	LIC GUID BR	1	1
	LIC QUAL BR	1	1	MATL ENG BR	1	1
	MECH ENG BR	1	1	MPA	11	3
	NRC PDR 02	1	1	OP EX EVAL BR	3	3
	OR ASSESS BR	1	1	POWER SYS BR	1	1
	PROC/TST REV BR	1	1	QA BR	1	1
	RAD ASSESS BR	1	1	REACT SYS BR	1	1
	REG FILE 01	1	1	REL & RISK A BR	1	1
	SFTY PROG EVAL	1	1	SIT ANAL BR	1	1
	STRUCT ENG BR	1	1	SYS INTERAC BR	1	1
EXTERNAL:	ACRS	6	0	LPDR 03	1	1
	NSIC 04	1	1	TERA: DOUG MAY	1	1

AUG 15 1980

*ADH*  
4  
60

TOTAL NUMBER OF COPIES REQUIRED: LTR 72 ENCL 66

