

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8103050578 DOC. DATE: 81/02/26 NOTARIZED: NO DOCKET #  
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331  
 AUTH. NAME: AUTHOR AFFILIATION  
 RAGER, M.S. Iowa Electric Light & Power Co.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 Region 3, Chicago, Office of the Director

SUBJECT: LER 81-006/03L-0: on 810127, during normal operation, containment pressure recorder PR 4384A failed upscale. Caused by bad connection due to bent pins on amplifier card for pen 1. Pins reoriented.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1/1  
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	IPPOLITO, T. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	ASLBP/J.HARD	1	1
	AUX SYS BR 15	1	1	CHEM ENG BR 16	1	1
	CONT SYS BR 17	1	1	CORE PERF BR 18	1	1
	DIR, DIV OF LIC	1	1	DIR, ENGINEER I20	1	1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	2	2	JORDAN, E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	MPA	3	3
	NRC PDR 02	1	1	OP EX EVAL BR34	3	3
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	<del>REG FILE</del> 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
	SYS INTERAC B45	1	1			
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1	TERA: DOUG MAY	1	1

MAR 09 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 68 ENCL 68

JF

