

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8105110316 DOC. DATE: 81/05/05 NOTARIZED: NO DOCKET #
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH. NAME: AUTHOR AFFILIATION:
 RAGER, M.S. Iowa Electric Light & Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION:
 Region 3, Chicago, Office of the Director

SUBJECT: Updated 79-023/03X-1: on 790917, control bldg standby filter unit, 1V-SFU-30A, did not automatically start when initiated. Caused by instrument drift & sticking damper lever. Instrument FT 7320B recalibr.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 2
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	IPPOLITO, T. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP. REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	AEOD/DMU	3	3
	ASLBP/J. HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR, ENGINEER I20	1	1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	1	1	JORDAN, E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	NRC PDR 02	1	1
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	<u>REG. FILE</u> 01	1	1	REL & RISK A 41	1	1
	SFTY PROG. EVA42	1	1	STRUCT ENG BR44	1	1
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1			

MAY 12 1981

A0/1
4

VB

TOTAL NUMBER OF COPIES REQUIRED: LTR 61 ENCL 61

