# REGULATRY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8903210481 DOC. DATE: 89/03/15 NOTARIZED: NO DOCKET # FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331

AUTH. NAME AUTHOR AFFILIATION

MINECK, D. L. Iowa Electric Light & Power Co.

RECIP. NAME

RECIPIENT AFFILIATION

MURLEY, T. E. Office of Nuclear Reactor Regulation, Director (Post 870411

SUBJECT: Forwards "Reactor Containment Bldg Integrated Leak Rate

Test" for 1988 refueling outage.

NOTES: See Reports

	RECIPIENT	COPI	ES	RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	PD3-3 LA	1	0	PD3-3 PD	5	5
	HALL, J. R.	1	1		·	
INTERNAL:	ACRS	6	6	ARM/DAF/LFMB	1	0
	NRR/DEST/PSB 8D	i	1	NUDOCS-ABSTRACT	1	1
	OGC/HDS2	i	1	REG FILE 01	1	1
	RES TELFORD, J	i	1	RESTDETSEB	1	1
,	RES/DSIR/SAIB	i	1	RES/DSR/RPSB	1	1
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

MAN!

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8903210481 DOC.DATE: 89/93/15 NOTARIZED: NO DOCKET # FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331 AUTH NAME AUTHOR AFFILIATION

MINECK, D.L. Iowa Electric Light & Power Co.
RECIP. NAME RECIPIENT AFFILIATION

Office of Nuclear Reactor Regulation, Director (Post 870411 MURLEY, T.E.

SUBJECT: Forwards "Reactor Containment Bldg Integrated Leak Rate Test" for 1988 refueling outage.

DISTRIBUTION CODE: A017D COPIES RECEIVED:LTR | ENCL | SIZE: /+7[ TITLE: OR Submittal: Append J Containment Leak Rate Testing

#### NOTES:

	ID CODE/NAME	· ·	ENCL	RECIPIENT ID CODE/NAME PD3-3 PD ARM/DAF/LFMB		IES ENCL	131
NTERNAL:	ACRS COMMISSION ACRS COMMISSION ACRS COMMISSION ACRES TELFORD, JRES/DSIR/SAIB	6 1 1 1	6 1 1 1	ARM/DAF/LFMB NUDOCS-ABSTRACT REG FILE 01 RES/DE/SEB RES/DSR/RPSB	1 1 1 1	0 1 1 1	
EXTERNAL:	LPDR NSIC	1	1	NRC PDR	1	1	

## NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

### Iowa Electric Light and Power Company

March 15, 1989 NG-89-0723

Dr. Thomas E. Murley, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Station P1-137 Washington D.C. 20555

Subject:

Duane Arnold Energy Center

Docket No. 50-331

Operating License No. DPR-49

Reactor Containment Building Integrated Leak Rate Test

and Local Leak Rate Test

File

A-103, T-23i, A-100

Dear Dr. Murley,

In accordance with Appendix A to Operating License DPR-49, Technical Specifications, Sections 6.11.3 and 4.7.A.2.g, and 10 CFR Part 50, Appendix J, Section V.B, please find attached a copy of the Duane Arnold Energy Center (DAEC) "Reactor Containment Building Integrated Leak Rate Test" for the 1988 Refueling Outage. Included as appendices to this report are the results and analysis of the Type B and Type C tests that were also performed prior to and during the refueling outage.

As documented in the attached report, testing conducted prior to startup from the 1988 Refueling Outage demonstrated that the DAEC primary containment leakage rate is within allowable limits. The next Type A test is currently scheduled to occur during the Cycle 10/11 Refueling Outage in 1990.

I trust you will find the information provided satisfactory. Should you have any questions regarding this submittal, please contact this office.

B903210481 B90315 PDR ADDCK 05000331 Very truly yours,

Daniel L. Mineck

Manager, Nuclear Division

DLM/RW/sb

Attachment: Reactor Containment Building Integrated Leak Rate Test

cc: R. Woodward

R. McGaughy

L. Liu

L. LIU

L. Root

NRC Resident Inspector
A. Bert Davis (NRC-RIII)

J.R. Hall (NRC-NRR)