



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PA 19406-1415

September 1, 2011

Mr. Thomas P. Joyce
President and Chief Nuclear Officer
PSEG Nuclear LLC - N09
P.O. Box 236
Hancocks Bridge, NJ 08038

SUBJECT: MID-CYCLE LETTER FOR SALEM NUCLEAR GENERATING STATION,
UNIT NOS. 1 AND 2 (REPORT 05000272/2011006 and 05000311/2011006)

Dear Mr. Joyce:

On August 11, 2011, the NRC completed its mid-cycle performance review of Salem Nuclear Generating Station. The NRC reviewed the most recent quarterly performance indicators (PIs) in addition to inspection results and enforcement actions from July 1, 2010, through June 30, 2011. This letter informs you of the NRC's assessment of your facility during this period and its plans for future inspections at your facility. This performance review and enclosed inspection plan do not include security information. A separate letter will include the NRC's assessment of your performance in the Security Cornerstone and its security-related inspection plan.

The NRC determined the performance at Salem Nuclear Generating Station during the most recent quarter was within the Licensee Response Column of the NRC's Reactor Oversight Process (ROP) Action Matrix because all inspection findings had very low (i.e., green) safety significance, and all PIs indicated that your performance was within the nominal, expected range (i.e., green). Therefore, the NRC plans to conduct ROP baseline inspections at your facility.

The enclosed inspection plan lists the inspections scheduled through December 31, 2012. Routine inspections performed by resident inspectors are not included in the inspection plan. The inspections listed during the last nine months of the inspection plan are tentative and may be revised at the end-of-cycle performance review. The NRC provides the inspection plan to allow for the resolution of any scheduling conflicts and personnel availability issues. In addition to the baseline inspections, we plan to conduct an inspection of your ISFSI. The NRC will contact you as soon as possible to discuss changes to the inspection plan should circumstances warrant any changes.

In the days following the Fukushima Daiichi nuclear accident in Japan, the Commission directed the staff to establish a senior-level agency task force to conduct a methodical and systematic review of the NRC's processes and regulations to determine whether the agency should make additional improvements to its regulatory system. The NRC has since completed Temporary Instruction (TI) 183, "Follow-up to Fukushima Daiichi Nuclear Station Fuel Damage Event," and TI-184, "Availability and Readiness Inspection of Severe Accident Management Guidelines (SAMGs)" at your facility. Results of these inspections can be found here: <http://www.nrc.gov/japan/japan-activities.html>. Additionally, on May 11, 2011, the agency issued NRC Bulletin 2011-01, "Mitigating Strategies," to confirm compliance with Order

EA-02-026, subsequently imposed license conditions, and 10 CFR 50.54(hh)(2), and to determine the status of licensee mitigating strategies programs. On July 12, 2011, the NRC's Task Force made its recommendations to the Commission in its report, "Recommendations for Enhancing Reactor Safety in the 21st Century: The Near-Term Task Force Review of Insights from the Fukushima Daiichi Accident." The NRC is currently reviewing the Task Force's recommendations to determine what additional actions may be warranted.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at 610-337-5069 with any questions you have regarding this letter.

Sincerely,

A handwritten signature in black ink, appearing to read "Arthur L. Burritt", written in a cursive style.

Arthur L. Burritt, Chief
Projects Branch 3
Division of Reactor Projects

Docket Nos. 50-272, 50-311
License Nos. DPR-70, DPR-75

Enclosure: Inspection Plan

cc w/encl: Distribution via ListServ

EA-02-026, subsequently imposed license conditions, and 10 CFR 50.54(hh)(2), and to determine the status of licensee mitigating strategies programs. On July 12, 2011, the NRC's Task Force made its recommendations to the Commission in its report, "Recommendations for Enhancing Reactor Safety in the 21st Century: The Near-Term Task Force Review of Insights from the Fukushima Daiichi Accident." The NRC is currently reviewing the Task Force's recommendations to determine what additional actions may be warranted.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Please contact me at 610-337-5069 with any questions you have regarding this letter.

Sincerely,

/RA/

Arthur L. Burritt, Chief
Projects Branch 3
Division of Reactor Projects

Docket Nos. 50-272, 50-311
License Nos. DPR-70, DPR-75

Enclosure:
Inspection Plan

cc w/encl: Distribution via ListServ

Distribution: See attached page

SUNSI REVIEW COMPLETE: ALB (Reviewer's Initials) ML112411294

DOCUMENT NAME: S:\ROP-12 MID-CYCLE REVIEW\BRANCH 3\LETTERS(ATTACHMENT1)\
SALEM MID-CYCLE LETTER2011.DOCX

After declaring this document "An Official Agency Record" it **will** be released to the Public.

To receive a copy of this document, indicate in box: "C" = Copy w/o attachment/enclosure, "E" = Copy w/ attachment/enclosure "N" = No copy

OFFICE <i>mmt</i>	RI/DRP	RI/DRP	R/DRP
NAME	DSchroeder/ LC for	LCline/ LC	ABurritt/ALB
DATE	08/ 26 /11	08/26 /11	08/29/11

OFFICIAL RECORD COPY

Distribution w/encl:

W. Dean, RA (R1ORAMAIL Resource)
D. Lew, DRA (R1ORAMAIL Resource)
D. Roberts, DRP (R1DRPMAIL Resource)
J. Clifford, DRP (R1DRPMAIL Resource)
C. Miller, DRS (R1DRSMail Resource)
P. Wilson, DRS (R1DRSMail Resource)
A. Burritt, DRP
L. Cline, DRP
A. Turilin, DRP
C. Douglas, DRP
D. Schroeder, DRP, SRI
P. McKenna, DRP, RI
K. McKenzie, DRP, OA
J. McHale, RI OEDO
DRS Branch Chiefs (6)
N. McNamara, RI, SLO
D. Tift, RI, SLO
D. Screnci, RI, PAO
N. Sheehan, RI, PAO
R. Barkley, RI, ORA
RidsNrrPMSalem Resource
RidsNrrDorLpl1-2 Resource
ROPreports Resource
RidsNrrDirslpab Resource
ROPassessment Resource

Salem

Inspection / Activity Plan

07/01/2011 - 12/31/2012

Unit Number	Planned Dates Start	Planned Dates End	Inspection Activity	Title	No. of Staff on Site
			0912EXM	- OPERATOR LICENSING INITIAL EXAMS	4
1	08/15/2011	08/19/2011	U01830	FY11- SALEM, INITIAL OL EXAM	
1	09/19/2011	09/23/2011	U01830	FY11- SALEM, INITIAL OL EXAM	
			71152	- PI&R	4
1,2	06/27/2011	07/01/2011	IP 71152B	Problem Identification and Resolution	
1,2	07/18/2011	07/22/2011	IP 71152B	Problem Identification and Resolution	
			711111B	- SALEM REQUAL INSP W/ P/F RESULTS	2
1,2	08/22/2011	08/26/2011	IP 7111111B	Licensed Operator Requalification Program	
			ISFSI	- ISFSI INSPECTION	1
1,2	07/15/2011	08/19/2011	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants	
			71124	- REMP	1
1,2	07/25/2011	07/29/2011	IP 71124.07	Radiological Environmental Monitoring Program	
			71124	- HP	1
1,2	10/31/2011	11/04/2011	IP 2515/179	Verification of Licensee Responses to NRC Requirement for Inventories of Materials Tracked in NSTS	
1,2	10/31/2011	11/04/2011	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants	
1	10/31/2011	11/04/2011	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1	10/31/2011	11/04/2011	IP 71124.02	Occupational ALARA Planning and Controls	
1	10/31/2011	11/04/2011	IP 71124.05	Radiation Monitoring Instrumentation	
			7111108P	- U1 INSERVICE INSPECTION	1
1	11/07/2011	11/18/2011	IP 7111108P	Inservice Inspection Activities - PWR	
			71124	- RADWASTE	2
1,2	12/05/2011	12/09/2011	IP 71124.08	Radioactive Solid Waste Processing and Radioactive Material Handling, Storage, and Transportation	
			TRI FIRE	- TRIENNIAL FIRE PROTECTION INSPECTION	6
1,2	01/23/2012	01/27/2012	IP 7111105T	Fire Protection [Triennial]	
1,2	02/06/2012	02/10/2012	IP 7111105T	Fire Protection [Triennial]	
			71124.06	- PUB RAD SAFETY - RETS	1
1,2	01/30/2012	02/03/2012	IP 71124.05	Radiation Monitoring Instrumentation	
1,2	01/30/2012	02/03/2012	IP 71124.06	Radioactive Gaseous and Liquid Effluent Treatment	
			71124	- OCC RDA SAFETY	1
1,2	03/12/2012	03/16/2012	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
1,2	03/12/2012	03/16/2012	IP 71124.02	Occupational ALARA Planning and Controls	
1,2	03/12/2012	03/16/2012	IP 71124.05	Radiation Monitoring Instrumentation	
			EP EX	- EP EXERCISE EVALUATION	5
1,2	05/21/2012	05/25/2012	IP 7111401	Exercise Evaluation	

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Salem

Inspection / Activity Plan

07/01/2011 - 12/31/2012

Unit Number	Planned Dates Start End	Inspection Activity	Title	No. of Staff on Site
		EP EX - EP EXERCISE EVALUATION		5
1, 2	05/21/2012 05/25/2012	IP 7111404	Emergency Action Level and Emergency Plan Changes	
		71124 - OCC RAD SAFETY		1
1, 2	06/11/2012 06/15/2012	IP 71124.02	Occupational ALARA Planning and Controls	
1, 2	06/11/2012 06/15/2012	IP 71124.03	In-Plant Airborne Radioactivity Control and Mitigation	
1, 2	06/11/2012 06/15/2012	IP 71124.04	Occupational Dose Assessment	
1, 2	06/11/2012 06/15/2012	IP 71124.05	Radiation Monitoring Instrumentation	
		11/19EXM - SALEM INITIAL EXAM		3
1	10/22/2012 10/26/2012	U01859	FY13-SALEM INITIAL OPERATOR LICENSING EXAM	
1	11/19/2012 11/23/2012	U01859	FY13-SALEM INITIAL OPERATOR LICENSING EXAM	
		71124 - RAD SAFETY		1
1, 2	10/22/2012 10/26/2012	IP 60855.1	Operation of an Independent Spent Fuel Storage Installation at Operating Plants	
2	10/22/2012 10/26/2012	IP 71124.01	Radiological Hazard Assessment and Exposure Controls	
2	10/22/2012 10/26/2012	IP 71124.02	Occupational ALARA Planning and Controls	
1, 2	10/22/2012 10/26/2012	IP 71151-OR01	Occupational Exposure Control Effectiveness	
1, 2	10/22/2012 10/26/2012	IP 71151-PR01	RETS/ODCM Radiological Effluent	
		7111108P - U2 INSERVICE INSPECTION		1
2	10/22/2012 11/02/2012	IP 7111108P	Inservice Inspection Activities - PWR	

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.