

**From:** Larry Arbogast (USA - Christensen Ranch) [Larry.Arbogast@uranium1.com]  
**Sent:** Thursday, August 25, 2011 1:23 PM  
**To:** Linton, Ron  
**Cc:** Spitzberg, Blair; Bill Kearney (USA - Casper); Tim McCullough (USA - Casper)  
**Subject:** Excursion

Dear Ron,

AS per license condition 12.2, Uranium One is reporting the confirmed excursion of monitor well 2MW108. On August 23, 2011 during routine quarterly sampling 2MW108 exceeded two upper control limits (UCLs). A second sample was taken on August 24, 2011 again two (UCLs) were exceeded. The (UCLs) that were exceeded are chloride 12.2 mg/l (UCL 11.6) and alkalinity 127.2 mg/l (UCL 124.6). 2MW108 is a perimeter ore zone monitor well in mine unit 2 a restored wellfield. Corrective action will begin as soon as pumps can be reset and piping reconnected. A written report on this matter will be sent in the allotted time frame.

Should you have any questions regarding this matter please call me anytime.

Larry

Thank You

Larry Arbogast  
Radiation Safety Officer  
Uranium One  
907 North Poplar, Suite 260  
Casper, Wyoming 82601  
(307)464-1427 ext. 34  
cell (307)267-4623