


Construction Programmatic SDP



		AP 1000 Construction Significance Determination Matrix			
Quality of Construction	Row 4				
	Row 3				
	Row 2				
	Row 1				
		Very Low	Low	Intermediate	High
		System/Structure Risk Importance			

Y – Axis Flow Diagram

